





report date: 2024-03-29

General information

Make	VOLVO
Model	S90 D4 MOMENTUM
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque 400 Nm at 1.750 rp	
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	43.5 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2022-10-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-07-03

Pictures 17

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date 2021-06-05

Pictures 16

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



YN680PE

report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-12
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	5
Total items failed	1

MOT #6	2023-12-13 11:45
MOT test number	111418436133
Result	✓ Passed
Next expiry date	2024-12-12

MOT #5	2023-12-12 10:14
MOT test number	703093877479
Result	X Failed
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #4	2023-06-16 09:49
MOT test number	909406528119
Result	✓ Passed
MOT #3	2022-12-17 10:30
MOT test number	582620177956
Result	✓ Passed

CarCheck.co.uk page 3/11



YN680PE

report date: 2024-03-29

MOT #2		2022-05-30 08:43
MOT test	number	570114069674
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #1	2021-05-18 15:16
MOT test number	828799387771
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 12 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

,	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NP. AS UK
Plate since	
Current registration	AIR UK
Plate since	
	More info

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



YN680PE

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-10-23
Last registration	2023-12-13
Complete history	See info



Registration #1	2018-10-23	12 mi
Registration #2	2021-05-18	26.530 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5	2022-05-30	36.032 mi
•		
Registration #6		11.777 es
		11.777 ea 11.777 ea
Registration #6		11.777 ea 11.777 ea 11.777 ea
Registration #6 Registration #7		11.777-00 11.777-00 11.777-00

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1697 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	55 l	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles2Engine number2571962