





report date: 2024-03-29

General information

| Make | CITROEN |
|---------------------|--------------------|
| Model | DS3 PURETECH FLAIR |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 80 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-09-04

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-09-04 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-10-28 |
|--------------------|------------|
| not expiry dute | 2027 10 20 |
| MOT pass rate | 67 % |
| MOT passed | 6 |
| Failed MOT tests | 3 |
| Total advice items | 16 |
| Total items failed | 2 |

| MOT #9 | 2023-10-17 09:45 |
|--|------------------|
| MOT test number | 149138110624 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-28 |
| Minor Offside Drive shaft joint constant velocity boot severely deteriorated CLIP (6.1.7 | ' (g) (i)) |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #8 | | 2022-10-24 11:10 |
|----------|--|------------------|
| MOT test | number | 751654033303 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii)) | |

| MOT #7 | 2022- | 10-24 11:10 |
|---|--|-----------------|
| MOT test number | 468 | 3395379662 |
| Result | | X Failed |
| Pass with rectification | Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii)) | | |
| Pass with rectification | Windscreen wiper does not clear the windscreen effectively (3.4 (b) (i | i)) |

CarCheck.co.uk page 3/12



MOT #6 2021-10-15 10:57

MOT test number 336462807441

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2021-10-08 15:45

MOT test number 203324730741

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Front Obligatory mirror missing (3.3 (a))

MOT #4 2020-10-29 16:35

MOT test number 990813894692

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2020-10-29 10:54

MOT test number 613103147419

Result ★ Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



MOT #2 2019-08-15 11:12

MOT test number 642390244383

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-03-28 15:35

MOT test number 272832900179

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 154 |
| MOT expiry date | 28 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e when miscory | | |
|---|-----------|-----|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | | OEN |
| ************************************** | | |
| | | |
| *************************************** | | |
| ********* | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this CITROEN had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courts at info | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileago registrations | 12 |
| Mileage registrations | 12 |
| First mileage registration | 2015-04-27 |
| Last registration | 2023-10-17 |
| Complete history | See info |



| Registration #1 | 2015-04-27 | 23 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-03-28 | 10.320 mi |
| Registration #3 | 2019-08-15 | 16.308 mi |
| Registration #4 | 2020-10-29 | 25.165 mi |
| Registration #5 | 2020-10-29 | 25.165 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 71.777 es |

More info >

CarCheck.co.uk page 11/12



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



Dimensions & weight

| Width | 1729 mm |
|---------------------|---------|
| Height | 1480 mm |
| Length | 4157 mm |
| Wheel base | 2595 mm |
| Kerb weight | 965 kg |
| Max. allowed weight | 1500 kg |

Additional information

| Fuel tank capacity | 50 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B2150067940 |

CarCheck.co.uk page 12/12