



EY05HGM

report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | FORD |
| Model | MONDEO ZETEC 16V |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 118 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 145 BHP |
| Max. torque | 190 Nm at 4.500 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 21.6 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 30.1 mpg |








Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-03 |
| Pictures | 15 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #22 | 2023-06-10 12:16 |
| MOT test number | 430280187379 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-09 |
| Advice | Brake pipe corroded, covered in grease or other material front/rear (1.1.11 (c)) |
| Minor | Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) |
| Advice | Oil leak, but not excessive engine (8.4.1 (a) (i)) |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b)) |
| Advice | Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) |

| | |
|--------------------------------|---|
| MOT #21 | 2023-06-10 12:16 |
| MOT test number | 730750471349 |
| Result | ✗ Failed |
| Pass with rectification | Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Advice | Brake pipe corroded, covered in grease or other material front/rear (1.1.11 (c)) |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Minor | Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) |
| Advice | Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b)) |
| Advice | Oil leak, but not excessive engine (8.4.1 (a) (i)) |
| Advice | Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) |

| | |
|------------------------|---|
| MOT #20 | 2022-06-10 12:39 |
| MOT test number | 668048071729 |
| Result | ✓ Passed |
| Advice | Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Advice | Oil leak, but not excessive engine (8.4.1 (a) (i)) |

**MOT #19**

2022-06-09 08:57

MOT test number

644421510377

Result

✗ Failed

Fail Nearside Rear Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Fail Front Road wheel fixing missing both side (5.2.1 (a) (i))

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Fail Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm inner/outer (5.2.3 (e))

Fail Rear Road wheel fixing missing both side (5.2.1 (a) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

2021-06-08 09:45

MOT test number

559515462729

Result

✓ Passed

Advice Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #17

2021-06-08 09:00

MOT test number

733668610671

Result

✗ Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16** 2020-06-09 16:53**MOT test number** 617946442041**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15** 2020-06-09 14:19**MOT test number** 842737414703**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2019-08-09 08:22**MOT test number** 128338973628**Result** ✓ Passed**MOT #13** 2018-08-10 15:15**MOT test number** 957027220400**Result** ✓ Passed**MOT #12** 2017-08-18 15:09**MOT test number** 335725840081**Result** ✓ Passed**MOT #11** 2016-08-20 08:06**MOT test number** 772217929480**Result** ✓ Passed**MOT #10** 2015-08-22 09:03**MOT test number** 396314235482**Result** ✓ Passed

**MOT #9** 2014-08-09 09:11**MOT test number** 778761524263**Result** ✓ Passed**MOT #8** 2013-08-12 08:58**MOT test number** 738194623209**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2012-08-18 10:02**MOT test number** 899481232262**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Off side rear tyre worn on inner edge**MOT #6** 2011-08-13 09:02**MOT test number** 236975721237**Result** ✓ Passed**MOT #5** 2010-08-20 10:26**MOT test number** 511692830296**Result** ✓ Passed**MOT #4** 2009-08-13 08:13**MOT test number** 934925829218**Result** ✓ Passed



| | |
|-------------------------|--|
| MOT #3 | 2008-09-08 16:14 |
| MOT test number | 363302558443 |
| Result | ✗ Failed |
| Pass with rectification | Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |

| | |
|-----------------|------------------|
| MOT #2 | 2008-09-08 16:14 |
| MOT test number | 674202258262 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2008-04-03 15:19 |
| MOT test number | 972254898026 |
| Result | ✓ Passed |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | EY05HGM |
| Plate since | 2019-03-28 |
| Current registration | EY05HGM |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2005-05-06 |
| Last registration | 2023-06-10 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2005-05-06 | 17 mi |
| Registration #2 | 2008-04-03 | 8.289 mi |
| Registration #3 | 2008-09-08 | 8.652 mi |
| Registration #4 | 2009-08-13 | 14.789 mi |
| Registration #5 | 2010-08-20 | 22.540 mi |
| Registration #6 | 2011-08-13 | 29.131 mi |
| Registration #7 | 2012-08-18 | 36.834 mi |
| Registration #8 | 2013-08-12 | 44.866 mi |
| Registration #9 | 2014-08-09 | 51.654 mi |
| Registration #10 | 2015-08-22 | 57.267 mi |
| Registration #11 | 2016-08-20 | 62.575 mi |
| Registration #12 | 2017-08-18 | 69.082 mi |
| Registration #13 | 2018-08-16 | 75.589 mi |
| Registration #14 | 2019-08-14 | 82.096 mi |
| Registration #15 | 2020-08-12 | 88.603 mi |
| Registration #16 | 2021-08-10 | 95.110 mi |
| Registration #17 | 2022-08-08 | 101.617 mi |
| Registration #18 | 2023-08-06 | 108.124 mi |
| Registration #19 | 2024-08-04 | 114.631 mi |
| Registration #20 | 2025-08-02 | 121.138 mi |
| Registration #21 | 2026-07-31 | 127.645 mi |
| Registration #22 | 2027-07-29 | 134.152 mi |
| Registration #23 | 2028-07-27 | 140.659 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1931 mm |
| Height | 1429 mm |
| Length | 4731 mm |
| Wheel base | 2754 mm |
| Kerb weight | 1415 kg |
| Max. allowed weight | 1950 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 58 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 5G46133 |