



report date: 2024-03-28

General information

Make	BMW
Model	530 530I SPORT
Colour	Black
Year of manufacture	2003
Top speed	152 mph
0 - 60 mph	7.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.500 rpm
Engine capacity	2.979 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	26.4 mpg
CO2 emission	257 g/km
CO2 label	M







Internet history

Entry 4


Date	2021-12-26
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 3

Date	2021-10-27
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-07-26
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1


Date	2021-05-24
------	------------

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-29
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	73
Total items failed	14

MOT #24	2023-12-20 15:18
MOT test number	719002028360
Result	✓ Passed
Next expiry date	2024-12-29

MOT #23	2022-12-21 13:18
MOT test number	107094592511
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #22	2022-12-20 16:47
MOT test number	250508980728
Result	✗ Failed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #21** 2021-12-30 13:52**MOT test number** 708592122725**Result** ✓ Passed**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #20** 2020-12-08 12:00**MOT test number** 923435156255**Result** ✓ Passed**Advice** Vehicle has engine covers & undertrays fitted obscuring view of some components**MOT #19** 2019-06-24 11:28**MOT test number** 340619689048**Result** ✓ Passed**MOT #18** 2018-06-29 10:07**MOT test number** 945711499807**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Front Brake hose slightly damaged (1.1.12 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Undertrays fitted obscuring testable items**Minor** Rear Brake hose slightly damaged (1.1.12 (b) (i))

**MOT #17**

2018-06-20 14:49

MOT test number

571997537915

Result**✗ Failed**

- Minor** Front Brake hose slightly damaged (1.1.12 (b) (i))
- Advice** Undertrays fitted obscuring testable items
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Rear Brake hose slightly damaged (1.1.12 (b) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #16

2017-06-21 15:03

MOT test number

819231154442

Result**✓ Passed**

- Advice** Offside Front Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Oil leak
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #15**

2016-08-08 17:40

MOT test number

935696568492

Result

✓ Passed

- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Slight play in steering rack inner joints
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #14

2016-08-08 10:49

MOT test number

639760240557

Result

✗ Failed

- Fail** Fuel cap/sealing device sealing washer deteriorated (7.2.4c)
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Slight play in steering rack inner joints
- Advice** Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

**MOT #13**

2015-08-25 11:38

MOT test number

320822786295

Result

✓ Passed

- Advice** Fuel cap seal cracking
- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Offside steering rack inner joint has some free play
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #12

2014-09-01 11:50

MOT test number

307804144218

Result

✓ Passed

- Notice** Fuel cap seal cracking
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Play in steering rack inner joint(s)
- Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)
- Notice** Oil leak
- Notice** Offside rear tyre has crack on inner side wall consistent with under inflation, not through to cords yet. ****Strong Advise****

**MOT #11**

2013-08-23 10:42

MOT test number

377015333440

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Fuel cap seal in poor condition**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Play in steering rack inner joint(s)**MOT #10**

2013-08-22 12:22

MOT test number

865954933255

Result

✗ Failed

Fail Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Front Headlamp levelling device obviously defective (1.7.2)**Notice** Fuel cap seal in poor condition**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Headlamp aim too low (1.8)**Notice** Play in steering rack inner joint(s)

**MOT #9** 2012-08-20 12:24**MOT test number** 326583732432**Result** ✓ Passed

- Notice** Stone chips across windscreen
- Notice** Offside inner steering rack joint noisy
- Notice** Both front tyres worn on inner edges
- Notice** Fuel cap seal cracked
- Notice** Play in steering rack inner joint(s)
- Notice** Nearside rear tyre has small cracks on inner sidewall
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #8 2011-08-09 15:53**MOT test number** 388291721409**Result** ✓ Passed

- Notice** Fuel cap seal starting to crack
- Notice** Offside front anti roll bar link ball joint boot split

MOT #7 2011-08-09 12:37**MOT test number** 988501521223**Result** ✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Offside front anti roll bar link ball joint boot split
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Fuel cap seal starting to crack

**MOT #6** 2010-08-19 12:18**MOT test number** 530621430262**Result** ✓ Passed**Notice** Rear number plate starting to delaminate**MOT #5** 2009-08-21 15:40**MOT test number** 532223139208**Result** ✓ Passed**MOT #4** 2008-08-22 10:09**MOT test number** 323895638405**Result** ✓ Passed**Notice** Off side front lower suspension arm slight movement in bush**MOT #3** 2008-08-21 12:10**MOT test number** 453704838280**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Off side front lower suspension arm slight movement in bush**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2007-08-22 11:11
MOT test number	963104437258
Result	✓ Passed
Notice	Rear brake pads low
Notice	Near side front tyre worn on inner edge. ⚠ Tracking?
Notice	Rear indicator bulbs starting to deteriorate

MOT #1	2006-06-30 11:20
MOT test number	691791386163
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
29 December 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-06-30
Last registration	2023-12-20
Complete history	See info



Registration #1	2003-06-30	24 mi
Registration #2	2006-06-30	33.852 mi
Registration #3	2007-08-22	43.430 mi
Registration #4	2008-08-21	52.957 mi
Registration #5	2008-08-22	52.957 mi
Registration #6	2009-08-21	60.417 mi
Registration #7	2010-08-19	66.847 mi
Registration #8	2011-08-09	74.693 mi
Registration #9	2011-08-09	74.693 mi
Registration #10	2012-08-20	82.698 mi
Registration #11	2013-08-22	90.778 mi
Registration #12	2013-08-23	90.778 mi
Registration #13	2014-09-01	98.543 mi
Registration #14	2015-08-25	104.660 mi
Registration #15	2016-08-08	110.270 mi
Registration #16	2016-08-08	110.270 mi
Registration #17	2016-08-08	110.270 mi
Registration #18	2016-08-08	110.270 mi
Registration #19	2016-08-08	110.270 mi
Registration #20	2016-08-08	110.270 mi
Registration #21	2016-08-08	110.270 mi
Registration #22	2016-08-08	110.270 mi
Registration #23	2016-08-08	110.270 mi
Registration #24	2016-08-08	110.270 mi
Registration #25	2016-08-08	110.270 mi
Registration #26	2016-08-08	110.270 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1800 mm
Height	1435 mm
Length	4775 mm
Wheel base	1558 mm

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	31652940