



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SPORT
Colour	Grey
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-04
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	36
Total items failed	0

MOT #15	2023-10-09 15:14
MOT test number	696978785863
Result	✓ Passed
Next expiry date	2024-10-08
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14	2023-10-03 15:11
MOT test number	649351521873
Result	✗ Failed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
DANGEROUS	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR	Brake pedal anti-slip provision missing (1.1.2 (c))
Advice	Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
MAJOR	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
DANGEROUS	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #13** 2022-08-17 14:57**MOT test number** 112964235410**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12** 2021-08-10 15:12**MOT test number** 579076351922**Result** ✓ Passed**MOT #11** 2020-11-16 12:54**MOT test number** 490946192679**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Power steering component has slight seepage from a component Steering rack (2.1.5 (a))**MOT #10** 2019-05-20 10:39**MOT test number** 241056324540**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both sides, inner edges (5.2.3 (e))

**MOT #9** 2019-05-18 11:56**MOT test number** 299059446279**Result** ✗ Failed**Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both sides, inner edges (5.2.3 (e))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #8** 2018-04-30 14:41**MOT test number** 516182762958**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #7** 2017-05-22 12:37**MOT test number** 701701402651**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-05-16 12:38**MOT test number** 379544303068**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit tread (4.1.E.1)**MOT #5** 2015-06-24 09:59**MOT test number** 297175775462**Result** ✓ Passed

**MOT #4** 2014-07-18 10:22**MOT test number** 845219594128**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Rear tyres mishaped slightly**MOT #3** 2013-07-19 09:03**MOT test number** 859350903280**Result** ✓ Passed**MOT #2** 2012-07-19 15:25**MOT test number** 525801902215**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2011-07-16 09:42**MOT test number** 496747491186**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 October 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-07-19
Last registration	2023-10-09
Complete history	See info



Registration #1	2008-07-19	23 mi
Registration #2	2011-07-16	32.045 mi
Registration #3	2012-07-19	43.254 mi
Registration #4	2013-07-19	54.458 mi
Registration #5	2014-07-18	62.112 mi
Registration #6	2015-06-24	70.759 mi
Registration #7	2016-05-16	78.032 mi
Registration #8	2017-05-22	84.719 mi
Registration #9	2018-04-30	95.109 mi
Registration #10	2019-05-22	101.277 mi
Registration #11	2020-05-22	101.277 mi
Registration #12	2021-05-22	101.277 mi
Registration #13	2022-05-22	101.277 mi
Registration #14	2023-05-22	101.277 mi
Registration #15	2024-05-22	101.277 mi
Registration #16	2025-05-22	101.277 mi
Registration #17	2026-05-22	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1289 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	153102