



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 100BHP
Colour	Silver
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg



LABEL UNKNOWN



Internet history

Entry 3



Date	2021-12-29
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2


Date	2021-06-25
Pictures	19
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-06-23
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #17	2022-08-05 15:30
MOT test number	467600721173
Result	✓ Passed
Next expiry date	2023-08-25
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Rear exhaust outer cover loose

MOT #16	2022-08-01 10:44
MOT test number	656673543980
Result	✗ Failed
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Rear exhaust outer cover loose
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #15** 2021-08-24 15:45**MOT test number** 632234226385**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Stone chip Zone A**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All round four (1.1.14 (a) (ii))**Advice** Various corrosion underneath**MOT #14** 2020-08-26 07:37**MOT test number** 940967522000**Result** ✓ Passed**MOT #13** 2019-05-22 10:39**MOT test number** 872905695173**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material several (1.1.11 (c))**Advice** Exhaust backbox deteriorating**MOT #12** 2018-05-21 13:59**MOT test number** 515784286192**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2017-05-13 09:34**MOT test number** 551920431015**Result** ✓ Passed

**MOT #10** 2016-05-26 14:43**MOT test number** 809375610166**Result** ✓ Passed**Advice** Rear tyres cracking**Advice** Corrosion on rear exhaust box**MOT #9** 2015-05-21 10:32**MOT test number** 289131545475**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-05-28 12:33**MOT test number** 687618444149**Result** ✓ Passed**MOT #7** 2012-02-14 15:52**MOT test number** 397675042036**Result** ✓ Passed**MOT #6** 2011-07-14 15:01**MOT test number** 275925091125**Result** ✓ Passed**MOT #5** 2010-07-21 18:06**MOT test number** 321832000461**Result** ✓ Passed**Notice** Oil leak**Notice** Front brake discs slightly worn and corroded

**MOT #4** 2010-02-03 15:04**MOT test number** 691774330091**Result** ✓ Passed**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**MOT #3** 2009-01-05 14:57**MOT test number** 901855709079**Result** ✓ Passed**MOT #2** 2008-01-04 12:25**MOT test number** 960554408072**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-01-04 11:48**MOT test number** 383434608025**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DF54CWX
Plate since	2019-06-29
Current registration	 DF54CWX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-01-05
Last registration	2022-08-05
Complete history	See info



Registration #1	2005-01-05	25 mi
Registration #2	2008-01-04	30.416 mi
Registration #3	2008-01-04	30.416 mi
Registration #4	2009-01-05	41.509 mi
Registration #5	2010-02-03	47.719 mi
Registration #6	2010-07-21	51.061 mi
Registration #7	2011-07-14	54.240 mi
Registration #8	2012-02-14	54.520 mi
Registration #9	2014-05-28	60.230 mi
Registration #10	2015-05-21	76.571 mi
Registration #11	2016-05-26	87.749 mi
Registration #12	2016-05-26	87.749 mi
Registration #13	2016-05-26	87.749 mi
Registration #14	2016-05-26	87.749 mi
Registration #15	2016-05-26	87.749 mi
Registration #16	2016-05-26	87.749 mi
Registration #17	2016-05-26	87.749 mi
Registration #18	2016-05-26	87.749 mi
Registration #19	2016-05-26	87.749 mi
Registration #20	2016-05-26	87.749 mi
Registration #21	2016-05-26	87.749 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1460 kg
Max. allowed weight	1833 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	AXR 143254