



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SPORT TSI
Colour	Blue
Year of manufacture	2006
Top speed	124 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.0 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-10-08
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-19
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-05
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	30
Total items failed	2

MOT #16	2023-11-06 13:01
MOT test number	946635087345
Result	✓ Passed
Next expiry date	2024-11-05
Advice	Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
Minor	Front Anti-roll bar linkage ball joint dust cover severely deteriorated Nearside & Offside (5.3.4 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2022-11-05 13:22
MOT test number	933696244392
Result	✓ Passed
Minor	Front Anti-roll bar linkage ball joint dust cover severely deteriorated Nearside & Offside (5.3.4 (b) (i))
Advice	Nearside Rear Nail in tyre

**MOT #14** 2022-11-05 13:22**MOT test number** 372769473006**Result** ✗ Failed**Minor** Front Anti-roll bar linkage ball joint dust cover severely deteriorated Nearside & Offside (5.3.4 (b) (i))**Advice** Nearside Rear Nail in tyre**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #13** 2021-10-27 15:50**MOT test number** 322737332220**Result** ✓ Passed**Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))**MOT #12** 2020-03-10 14:12**MOT test number** 162255812242**Result** ✓ Passed**MOT #11** 2019-03-13 13:25**MOT test number** 809106262488**Result** ✓ Passed**MOT #10** 2018-03-08 14:12**MOT test number** 420933958096**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both side (4.1.E.1)**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #9** 2017-03-10 13:56**MOT test number** 863117296089**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Tyre worn close to the legal limit both front (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Front wipers slightly deteriorated
- Advice** Nearside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #8** 2016-01-25 11:15**MOT test number** 101793980998**Result** ✓ Passed

- Advice** Front brake discs slightly pitted
- Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Wipers slightly deteriorated
- Advice** Tyre worn close to the legal limit both front (4.1.E.1)

**MOT #7** 2015-01-05 14:43**MOT test number** 807135305000**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #6** 2014-01-20 13:58**MOT test number** 538140924017**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2013-01-21 11:03**MOT test number** 459021923043**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2012-01-23 16:53**MOT test number** 509813922007**Result** ✓ Passed**MOT #3** 2011-01-28 13:27**MOT test number** 309018421019**Result** ✓ Passed

- Notice** Oil leak

**MOT #2** 2009-12-17 09:38**MOT test number** 131271759394**Result** ✓ Passed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #1** 2009-12-17 09:38**MOT test number** 634431159389**Result** ✗ Failed

- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	5 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-01
Last registration	2023-11-06
Complete history	<a href="#">See info</a>



Registration #1	2006-09-01	14 mi
Registration #2	2009-12-17	30.850 mi
Registration #3	2011-01-28	40.168 mi
Registration #4	2012-01-23	44.919 mi
Registration #5	2013-01-21	51.479 mi
Registration #6	2014-01-20	60.114 mi
Registration #7	2015-01-05	66.042 mi
Registration #8	2016-01-25	71.432 mi
Registration #9	2017-03-10	73.702 mi
Registration #10	2018-03-20	75.377 mi
Registration #11	2019-03-20	76.377 mi
Registration #12	2020-03-20	77.377 mi
Registration #13	2021-03-20	78.377 mi
Registration #14	2022-03-20	79.377 mi
Registration #15	2023-03-20	80.377 mi
Registration #16	2024-03-20	81.377 mi
Registration #17	2025-03-20	82.377 mi
Registration #18	2026-03-20	83.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1659 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BMY 005418