



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS TSI
Colour	Blue
Year of manufacture	2009
Top speed	135 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-09
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-02-06
Pictures	9
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-23
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #162023-09-09 11:12

MOT test number506331273745

Result✓ Passed

Next expiry date2024-09-23

- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Shock absorbers has light misting of oil (5.3.2 (b))
- Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15** 2022-09-20 08:14**MOT test number** 854776769137**Result** ✓ Passed**MOT #14** 2021-09-24 11:04**MOT test number** 757668645303**Result** ✓ Passed**MOT #13** 2021-07-02 10:42**MOT test number** 349415698643**Result** ✓ Passed**MOT #12** 2020-09-07 13:14**MOT test number** 776792506818**Result** ✓ Passed**Advice** Front Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))**Advice** Engine covers and under trays fitted obscuring some components**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #11** 2020-09-07 09:21**MOT test number** 585412186943**Result** ✗ Failed**Advice** Front Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))**Advice** Engine covers and under trays fitted obscuring some components**Fail** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10**

2019-05-17 08:03

MOT test number

554870717253

Result

✓ Passed

Advice Front Shock absorbers light misting of oil or has limited damping effect both have a light misting of oil (5.3.2 (b))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Engine covers and under trays fitted obscuring some components

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e))

MOT #9

2018-05-09 09:20

MOT test number

979131788296

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Front Tyre worn close to the legal limit 2.9mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit 2.9mm (4.1.E.1)

MOT #8

2017-05-08 13:11

MOT test number

186248800438

Result

✓ Passed

MOT #7

2016-05-12 15:19

MOT test number

327961013640

Result

✓ Passed

MOT #6

2015-05-28 17:18

MOT test number

169688245119

Result

✓ Passed

**MOT #5** 2015-05-28 14:01**MOT test number** 379998245178**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #4** 2014-08-28 15:56**MOT test number** 857360444289**Result** ✓ Passed**MOT #3** 2014-05-16 17:35**MOT test number** 168746634160**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #2** 2013-09-16 14:11**MOT test number** 116099653293**Result** ✓ Passed**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Both front tyres worn low on inner shoulders (tracking recommended)**MOT #1** 2012-09-11 15:13**MOT test number** 989525652289**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
23 September 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	23 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GU59FAO
Plate since	2024-03-28
Current registration	 GU59FAO
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-24
Last registration	2023-09-09
Complete history	See info



Registration #1	2009-09-24	23 mi
Registration #2	2012-09-11	12.908 mi
Registration #3	2013-09-16	17.861 mi
Registration #4	2014-05-16	21.189 mi
Registration #5	2014-08-28	22.461 mi
Registration #6	2015-05-28	26.120 mi
Registration #7	2015-05-28	26.120 mi
Registration #8	2016-05-12	31.340 mi
Registration #9	2017-05-08	35.750 mi
Registration #10	2018-05-09	40.966 mi
Registration #11	2019-05-09	45.182 mi
Registration #12	2020-05-09	49.398 mi
Registration #13	2021-05-09	53.614 mi
Registration #14	2022-05-09	57.830 mi
Registration #15	2023-05-09	62.046 mi
Registration #16	2023-05-09	62.046 mi
Registration #17	2023-05-09	62.046 mi
Registration #18	2023-05-09	62.046 mi
Registration #19	2023-05-09	62.046 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAV 101705