



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-29
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-03
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #14	2023-11-03 11:50
MOT test number	783575960714
Result	✓ Passed
Next expiry date	2024-11-03
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13	2022-11-04 13:07
MOT test number	367455121552
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-11-01 09:39
MOT test number	376041257276
Result	✓ Passed

MOT #11	2020-10-29 16:42
MOT test number	145827629538
Result	✓ Passed

**MOT #10** 2020-10-29 16:42**MOT test number** 731632498957**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #9** 2019-11-07 16:23**MOT test number** 197839791200**Result** ✓ Passed**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #8** 2019-11-07 16:23**MOT test number** 921752108584**Result** ✗ Failed**Pass with rectification** Offside Outer Body component damaged and likely to cause injury side repeater damaged causing a sharp edge (6.2.1 (a) (i))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #7** 2018-11-06 12:48**MOT test number** 265614353038**Result** ✓ Passed**Minor** Offside Side repeater lens defective which has no effect on emitted light damaged just visible from rear (4.4.1 (b) (i))**Advice** Both wiper blades a little smeary**MOT #6** 2017-12-05 09:17**MOT test number** 478496182351**Result** ✓ Passed

**MOT #5**

2015-09-16 10:22

**MOT test number**

792898394186

**Result**

✓ Passed

- Advice** Covers fitted to engine and under car
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Covers missing from wheel nuts on O/S/F wheel nuts
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4**

2015-09-15 15:38

**MOT test number**

788596866896

**Result**

✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Covers missing from wheel nuts on O/S/F wheel nuts
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords On tread (4.1.D.1a)
- Advice** Covers fitted to engine and under car

**MOT #3**

2014-10-03 14:11

**MOT test number**

428096274211

**Result**

✓ Passed

- Notice** Near side front tyre worn on inner edge
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Emissions to clean to register so no print out issued
- Notice** Off side front tyre heavily worn on inner edge



MOT #2	2014-10-01 13:12
MOT test number	466794674258
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Off side front tyre heavily worn on inner edge
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Notice	Near side front tyre worn on inner edge
Fail	Parking brake lever has no reserve travel (3.1.6b)
Notice	Emissions to clean to register so no print out issued

MOT #1	2013-09-09 12:54
MOT test number	498432953278
Result	✓ Passed
Notice	Emissions to clean to register so no print out issued
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
3 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	3 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-29
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2010-09-29	22 mi
Registration #2	2013-09-09	32.064 mi
Registration #3	2014-10-01	38.665 mi
Registration #4	2014-10-03	38.675 mi
Registration #5	2015-09-15	44.901 mi
Registration #6	2015-09-16	44.901 mi
Registration #7	2017-12-05	48.597 mi
Registration #8	2018-11-06	55.729 mi
Registration #9	2019-05-29	55.729 mi
Registration #10	2019-05-29	55.729 mi
Registration #11	2019-05-29	55.729 mi
Registration #12	2019-05-29	55.729 mi
Registration #13	2019-05-29	55.729 mi
Registration #14	2019-05-29	55.729 mi
Registration #15	2019-05-29	55.729 mi
Registration #16	2019-05-29	55.729 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1382 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	957548