



report date: 2024-03-28

General information

Make	LOTUS
Model	ELISE 111S
Colour	Grey
Year of manufacture	2003
Top speed	132 mph
0 - 60 mph	5.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	175 Nm at 4.650 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-26
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-27
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	10
Total items failed	5

MOT #22	2023-09-26 07:00
MOT test number	756672071263
Result	✓ Passed
Next expiry date	2024-09-27

MOT #21	2023-09-16 10:01
MOT test number	781175019825
Result	✗ Failed
<b>MAJOR</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #20	2022-09-23 10:06
MOT test number	465312132889
Result	✓ Passed

MOT #19	2021-09-02 13:44
MOT test number	387513767768
Result	✓ Passed
<b>Advice</b> Exhaust has a minor leak of exhaust gases flexi area (6.1.2 (a))	
<b>Minor</b> Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
<b>Advice</b> Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	

**MOT #18** 2020-09-03 08:14**MOT test number** 130022698063**Result** ✓ Passed**MOT #17** 2019-09-09 08:27**MOT test number** 533648378841**Result** ✓ Passed**MOT #16** 2018-09-19 07:32**MOT test number** 943220257723**Result** ✓ Passed**MOT #15** 2017-09-20 08:38**MOT test number** 722340730785**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases exhaust flexi pipe (7.1.2)**MOT #14** 2016-09-13 15:15**MOT test number** 748628791721**Result** ✓ Passed**MOT #13** 2016-09-13 08:51**MOT test number** 966538499243**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Fail** Offside Front Driver's door cannot be opened from outside the vehicle (6.2.B.1b)**MOT #12** 2015-09-22 08:10**MOT test number** 439242336350**Result** ✓ Passed

**MOT #11** 2014-09-12 14:27**MOT test number** 868355754218**Result** ✓ Passed**MOT #10** 2013-09-09 09:36**MOT test number** 589522653250**Result** ✓ Passed**MOT #9** 2012-09-13 12:14**MOT test number** 135967852219**Result** ✓ Passed**MOT #8** 2011-09-13 09:41**MOT test number** 816926651202**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2010-09-17 15:46**MOT test number** 682840760294**Result** ✓ Passed**MOT #6** 2010-09-17 15:46**MOT test number** 970610760255**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too high (1.8)

**MOT #5** 2009-09-18 09:26**MOT test number** 700041469285**Result** ✓ Passed**Notice** Rear registration plate deteriorating**Advice** Offside Rear Road wheel slightly damaged (4.2.A.1a)**MOT #4** 2008-09-25 15:43**MOT test number** 491939568273**Result** ✓ Passed**MOT #3** 2008-09-22 12:53**MOT test number** 910836268256**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #2** 2007-09-18 09:47**MOT test number** 841131967240**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-09-22 16:24**MOT test number** 542135566287**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
27 September 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	27 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this LOTUS. See if, where and when this LOTUS had damage and the car repair costs. We also check if this LOTUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LOTUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LOTUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this LOTUS? How many owners did this LOTUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LOTUS had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this LOTUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LOTUS has been settled.

If not, and you buy this LOTUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LOTUS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-27
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2003-09-27	20 mi
Registration #2	2006-09-22	18.127 mi
Registration #3	2007-09-18	24.826 mi
Registration #4	2008-09-22	37.183 mi
Registration #5	2008-09-25	37.183 mi
Registration #6	2009-09-18	41.212 mi
Registration #7	2010-09-17	45.016 mi
Registration #8	2011-09-13	47.015 mi
Registration #9	2012-09-13	48.589 mi
Registration #10	2013-09-09	50.396 mi
Registration #11	2014-09-12	51.579 mi
Registration #12	2015-09-22	53.040 mi
Registration #13	2016-09-22	55.277 mi
Registration #14	2017-09-22	57.514 mi
Registration #15	2018-09-22	59.751 mi
Registration #16	2019-09-22	61.988 mi
Registration #17	2020-09-22	64.225 mi
Registration #18	2021-09-22	66.462 mi
Registration #19	2022-09-22	68.699 mi
Registration #20	2023-09-22	70.936 mi
Registration #21	2024-09-22	73.173 mi
Registration #22	2025-09-22	75.410 mi
Registration #23	2026-09-22	77.647 mi

More info >



Dimensions & weight

Width	1701 mm
Height	1148 mm
Length	3276 mm
Wheel base	2300 mm
Kerb weight	806 kg

Additional information

Fuel tank capacity	38 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	18K4KP43555564