



report date: 2024-03-29

General information

Make	MAZDA
Model	2 TS2 ACTIVEMATIC
Colour	Blue
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	133 Nm at 4.000 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-05-23
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-07
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	5

MOT #12 2023-07-08 11:40

MOT test number 482842143576

Result ✓ Passed

Next expiry date 2024-07-07

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced underside vehicle corroded all subframe mounts front and rear have corrosion (6.1.1 (c) (i))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))

MOT #11 2022-07-04 09:06

MOT test number 737685171368

Result ✓ Passed

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))

MOT #10 2021-07-07 14:59

MOT test number 809102468837

Result ✓ Passed

**MOT #9**

2019-10-29 19:00

**MOT test number**

306116485758

**Result**

✓ Passed

- Advice** Steering system slightly rough (2.1.1 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8**

2018-10-23 11:27

**MOT test number**

280627139400

**Result**

✓ Passed

**MOT #7**

2018-10-20 08:34

**MOT test number**

701677168188

**Result**

✗ Failed

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Exhaust heat shields loose

**MOT #6** 2017-10-19 09:54**MOT test number** 423707897612**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-10-19 12:15**MOT test number** 380020242016**Result** ✓ Passed**MOT #4** 2015-10-06 10:27**MOT test number** 424695397577**Result** ✓ Passed**MOT #3** 2014-10-25 09:33**MOT test number** 357558794412**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #2** 2013-10-21 14:14**MOT test number** 549604893257**Result** ✓ Passed**MOT #1** 2013-10-19 10:56**MOT test number** 218262593211**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
7 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	7 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-28
Last registration	2023-07-08
Complete history	<a href="#">See info</a>



Registration #1	2010-10-28	12 mi
Registration #2	2013-10-19	16.249 mi
Registration #3	2013-10-21	16.290 mi
Registration #4	2014-10-25	22.203 mi
Registration #5	2015-10-06	27.753 mi
Registration #6	2016-10-19	32.166 mi
Registration #7	2017-10-19	36.547 mi
Registration #8	2018-10-20	41.277 mi
Registration #9	2019-10-20	46.277 mi
Registration #10	2020-10-20	51.277 mi
Registration #11	2021-10-20	56.277 mi
Registration #12	2022-10-20	61.277 mi
Registration #13	2023-07-08	66.277 mi
Registration #14	2024-03-29	71.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZY 700588