





# General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	White
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	130 g/km
CO2 label	D







# Internet history

Entry 3	
Date	2023-02-14
Pictures	20
Listing price	View report



source: autotrader.co.uk

Entry 2	
Date	2021-07-01
Pictures	6
Listing price	<u>View report</u>



source: autotrader.co.uk

Entry 1	
Date	2021-06-07
Pictures	6
Listing price	View report









source: autotrader.co.uk



# MOT history

MOT expiry date	2024-09-05
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	6

MOT #11		2023-09-06 15:05
MOT test	number	539062347010
Result		✓ Passed
Next expi	ry date	2024-09-05
Advice	Rear axle corroded	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #10	2023-08-31 11:18
MOT test number	176210946417
Result	🗙 Failed
Advice Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Fail</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear axle corroded	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

# MOT #9 2022-08-26 08:19 MOT test number 421313712631 Result ✓ Passed Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #8	2021-08-23 11:02	
MOT test number	397610172143	
Result	✓ Passed	
Advice Sub-frame corroded but not seriously weakened F & R SF'S/AXLE & ALL SA'S HSC-PODOT- MONITOR (5.3.3 (b) (i))		
Minor Rear Windscreen wiper blade defective (3.4 (b) (i))		



<b>CV61UEK</b>
report date: 2024-03-28

MOT #7	2021-08-09 11:36
MOT test number	547966431838
Result	🗙 Failed
<b>Fail</b> Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Fail</b> Rear Parking brake efficiency below requirements BOTH COMBINED =14%- (1.4.2	(a) (i))
Advice Sub-frame corroded but not seriously weakened F & R SF'S/AXLE & ALL SA'S HSC-PODOT- MONITOR (5.3.3 (b) (i))	
Minor Rear Windscreen wiper blade defective (3.4 (b) (i))	

MOT #6	2020-09-01 09:58
MOT test number	958261701252
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (	g) (i))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2019-09-03 13:21
MOT test number	702710737442
Result	✓ Passed
MOT #4	2017-10-11 08:45
MOT test number	703570106403
Result	✓ Passed
MOT #3	2016-10-04 09:50
MOT test number	329711394018

Result

🗸 Passed





MOT #2	2015-10-12 08:38
MOT test number	534067592768
Result	✓ Passed
MOT #1	2014-10-13 10:13
MOT test number	395446784491
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ мот
Tax due: 1 March 2025	<b>Expires:</b> 5 September 2024
Tax status	Valid until 1 March
Days left	307
MOT expiry date	5 September 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





# Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*********	
And a second sec	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	







### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-23
Last registration	2023-09-06
Complete history	See info



Registration #1	2011-09-23	8 mi
Registration #2	2014-10-13	22.655 mi
Registration #3	2015-10-12	34.504 mi
Registration #4	2016-10-04	44.688 mi
Registration #5	2017-10-11	56.764 mi
Registration #6	2019-09-03	83.878 mi
Registration #7	2020-09-01	92.997 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi





# Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	G4FABZ370121