



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI SE BLUE DRIVE
Colour	Black
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	11.8 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	76.4 mpg
Consumption combined	72.4 mpg
CO2 emission	109 g/km
CO2 label	B





MOT history

MOT expiry date	2024-12-16
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #9	2023-12-17 16:36
MOT test number	397072665515
Result	✓ Passed
Next expiry date	2024-12-16
Advice	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #8	2023-12-17 16:36
MOT test number	626931467127
Result	✗ Failed
Advice	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7	2022-08-30 14:23
MOT test number	813277232702
Result	✓ Passed
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Brake disc worn, pitted or scored, but not seriously weakened All 4 (1.1.14 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2021-07-16 16:39**MOT test number** 272926052045**Result** ✓ Passed**MOT #5** 2020-07-21 13:13**MOT test number** 949201830914**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #4** 2019-08-22 16:51**MOT test number** 546818018144**Result** ✓ Passed**Advice** Nearside Rear door is damaged but not sharp**MOT #3** 2019-08-22 11:01**MOT test number** 506904246075**Result** ✓ Passed**MOT #2** 2018-09-25 15:38**MOT test number** 316476432781**Result** ✓ Passed**Advice** Items removed from driver's view prior to test items on rear view mirror**MOT #1** 2018-09-25 14:07**MOT test number** 729449676776**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure in tread (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test items on rear view mirror



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
16 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	16 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-30
Last registration	2023-12-17
Complete history	See info



Registration #1	2015-09-30	9 mi
Registration #2	2018-09-25	17.902 mi
Registration #3	2018-09-25	17.902 mi
Registration #4	2019-08-22	25.408 mi
Registration #5	2019-08-22	25.425 mi
Registration #6	2019-08-22	25.425 mi
Registration #7	2019-08-22	25.425 mi
Registration #8	2019-08-22	25.425 mi
Registration #9	2019-08-22	25.425 mi
Registration #10	2019-08-22	25.425 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1465 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1456 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBFZ048122