



report date: 2024-03-28

General information

Make	KIA
Model	VENGA CRDI 3 ECODYNAMICS
Colour	Silver
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C









Internet history

Entry 2




Date	2021-02-01
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	10
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-06-15
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	15
Total items failed	21

MOT #16	2023-06-15 11:26
MOT test number	638907579846
Result	✓ Passed
Next expiry date	2024-06-15
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2022-05-28 09:54
MOT test number	894619830806
Result	✓ Passed

MOT #14	2021-06-16 09:18
MOT test number	831688509493
Result	✓ Passed

**MOT #13**

2021-06-10 09:55

**MOT test number**

288782085855

**Result**

✗ Failed

- Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn anti roll bar link (5.3.4 (a) (i))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2020-05-19 13:24

**MOT test number**

494821840871

**Result**

✓ Passed

**MOT #11**

2020-05-19 10:18

**MOT test number**

464071663041

**Result**

✗ Failed

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #10**

2019-05-15 14:21

**MOT test number**

578812543737

**Result**

✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9** 2019-05-15 09:39**MOT test number** 149351254374**Result** ✗ Failed

- Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt boot torn (5.3.4 (b) (ii))
- Fail** Offside Front Tyre has ply or cords exposed on inner edge (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on legal limit and cracking in tread area and wearing on inner edge (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre

**MOT #8** 2018-06-01 16:09**MOT test number** 320555860042**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-05-29 16:18**MOT test number** 645540624251**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #6** 2017-05-17 14:41**MOT test number** 887307763685**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #5** 2016-05-18 11:28**MOT test number** 871171336450**Result** ✓ Passed**Advice** Offside Front Upper Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt drop link (2.4.G.2)**MOT #4** 2015-06-10 16:44**MOT test number** 298491165416**Result** ✓ Passed**MOT #3** 2015-06-09 17:50**MOT test number** 539170165153**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-11-10 15:33**MOT test number** 927244414357**Result** ✓ Passed**MOT #1** 2014-11-10 15:33**MOT test number** 525674214392**Result** ✗ Failed**Pass with rectification** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Pass with rectification** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
15 June 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	15 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>ST61LKL</b>
Plate since	2019-03-28
Current registration	<b>ST61LKL</b>
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-11-28
Last registration	2023-06-15
Complete history	<a href="#">See info</a>



Registration #1	2011-11-28	22 mi
Registration #2	2014-11-10	28.150 mi
Registration #3	2015-06-09	34.741 mi
Registration #4	2015-06-10	34.741 mi
Registration #5	2016-05-18	44.952 mi
Registration #6	2017-05-17	54.308 mi
Registration #7	2018-05-29	63.194 mi
Registration #8	2018-06-01	63.195 mi
Registration #9	2019-05-15	71.408 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1370 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D4FCAZ012835
---------------	--------------