



CITROËN



CEI5VJU


report date: 2024-03-29

## General information

|                     |                  |
|---------------------|------------------|
| Make                | CITROEN          |
| Model               | DS3 E-HDI DSTYLE |
| Colour              | Yellow           |
| Year of manufacture | 2015             |
| Top speed           | 113 mph          |
| 0 - 60 mph          | 12.5 seconds     |
| Gearbox             | 5 speed Manual   |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 90 BHP              |
| Max. torque             | 230 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 64.2 mpg            |
| Consumption extra urban | 85.6 mpg            |
| Consumption combined    | 76.4 mpg            |
| CO2 emission            | 95 g/km             |
| CO2 label               | A                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-05-12                  |
| Pictures      | 17                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-03-20 |
| MOT pass rate      | 64 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 4          |
| Total advice items | 34         |
| Total items failed | 0          |

|                  |                  |
|------------------|------------------|
| MOT #11          | 2024-03-21 10:34 |
| MOT test number  | 535862273735     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-03-20       |

|   |                  |
|---|------------------|
| MOT #10   | 2024-03-18 13:33 |
| MOT test number   | 209404107786     |
| Result  | ✗ Failed         |
| <b>MAJOR</b> Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) |                  |
| <b>MAJOR</b> Windscreen washer provides insufficient washer liquid (3.5 (a))                                |                  |
| <b>DANGEROUS</b> Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                                |                  |
| <b>MAJOR</b> Reversing lamp inoperative (4.6.1 (a))   |                  |
| <b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))                    |                  |

|  |                  |
|--|------------------|
| MOT #9   | 2023-05-31 10:35 |
| MOT test number  | 254277220012     |
| Result   | ✓ Passed         |
| <b>Minor</b> Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |                  |
| <b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                                     |                  |

**MOT #8** 2022-05-10 07:55**MOT test number** 573985308703**Result** ✓ Passed**MOT #7** 2021-06-28 14:28**MOT test number** 572707274816**Result** ✓ Passed**MOT #6** 2021-06-28 12:27**MOT test number** 151527669910**Result** ✗ Failed

- MAJOR** Reversing lamp inoperative (4.6.1 (a))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #5** 2020-06-30 15:16**MOT test number** 576778269898**Result** ✓ Passed

- Advice** Offside Rear Brake disc slightly corroded
- Advice** Rear Exhaust mounting defective Bracket broken before rear silencer (6.1.2 (a))

**MOT #4**

2020-06-30 09:28

**MOT test number**

803459950427

**Result****✗ Failed****MAJOR** Nearside Reversing lamp inoperative (4.6.1 (a))**Advice** Rear Exhaust mounting defective Bracket broken before rear silencer (6.1.2 (a))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Brake disc slightly corroded**MOT #3**

2019-06-06 12:37

**MOT test number**

843884730117

**Result****✓ Passed****Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre**MOT #2**

2018-05-22 14:02

**MOT test number**

407251429086

**Result****✓ Passed****Advice** Front Exhaust leaking**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))



|   |                  |
|---|------------------|
| MOT #1  | 2018-05-21 12:31 |
| MOT test number   | 303350978200     |
| Result  | ✗ Failed         |
| <div><div>MAJOR</div>Windscreen washer provides insufficient washer liquid (3.5 (a))</div>                |                  |
| <div><div>DANGEROUS</div>Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div>      |                  |
| <div><div>Advice</div>Brake pad(s) wearing thin (1.1.13 (a) (ii))</div>                                   |                  |
| <div><div>DANGEROUS</div>Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div>     |                  |
| <div><div>Advice</div>Front Exhaust leaking</div>   |                  |
| <div><div>Minor</div>Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))</div> |                  |
| <div><div>DANGEROUS</div>Offside Front Tyre has ply or cords exposed 205/45/17 (5.2.3 (d) (ii))</div>     |                  |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
20 March 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 305                             |
| <b>MOT expiry date</b>  | 20 March 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | A              |
| <b>Single payment (12 months)</b>              | £ 0,00,-       |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | Not applicable |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 0   |
| Current registration |   |
| Plate since          | 2024-03-29  |
| Current registration |   |
| Plate since          | 2024-03-29  |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2015-03-31               |
| Last registration          | 2024-03-21               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2015-03-31 | 17 mi      |
| Registration #2  | 2018-05-21 | 32.099 mi  |
| Registration #3  | 2018-05-22 | 32.158 mi  |
| Registration #4  | 2019-06-06 | 47.266 mi  |
| Registration #5  | 2020-06-30 | 60.755 mi  |
| Registration #6  | 2020-06-30 | 60.755 mi  |
| Registration #7  | 2021-06-28 | 72.344 mi  |
| Registration #8  | 2022-06-29 | 85.277 mi  |
| Registration #9  | 2023-06-29 | 98.210 mi  |
| Registration #10 | 2024-03-21 | 111.143 mi |
| Registration #11 | 2024-03-21 | 111.143 mi |
| Registration #12 | 2024-03-21 | 111.143 mi |
| Registration #13 | 2024-03-21 | 111.143 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 87%                             |
| Children       | 71%                             |
| Pedestrian     | 35%                             |
| Safety systems | 83%                             |
| Overall rating | 73%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1728 mm |
| Height              | 1524 mm |
| Length              | 3941 mm |
| Wheel base          | 2464 mm |
| Kerb weight         | 1085 kg |
| Max. allowed weight | 1602 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 48 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 3                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | JBFM0107961      |