



GFIOE0U


report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Red
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-09
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	30
Total items failed	8

MOT #14	2023-09-25 09:12
MOT test number	869330179732
Result	✓ Passed
Next expiry date	2024-10-02
Advice	Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #13	2022-10-03 13:51
MOT test number	923460220183
Result	✓ Passed
Advice	Rear Lower Gearbox mounting defective split
Advice	Offside Rear of bumper and tailgate damaged
Advice	Offside Rear tyre worn on inner edge
Minor	Offside Front Headlamp lens slightly defective beam image only just visible (4.1.1 (b) (i))
Advice	Nearside Rear passenger door damaged
Advice	Nearside Front wheel-trim damaged leaving sharp edges
Advice	Coil spring corroded both rear (5.3.1 (b) (i))

**MOT #12**

2021-09-16 15:58

MOT test number

789875817130

Result

✓ Passed

- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear passenger door damaged
- Advice** Offside Rear Shock absorbers has a slightly worn bush split (5.3.2 (c))
- Advice** Rear Lower Gearbox mounting defective split
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush split (5.3.2 (c))

MOT #11

2021-09-16 12:28

MOT test number

353326350141

Result

✗ Failed

- Advice** Rear Lower Gearbox mounting defective split
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear tyre has deep cut in outer edge
- Advice** Offside Rear Shock absorbers has a slightly worn bush split (5.3.2 (c))
- Advice** Nearside Rear passenger door damaged
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear tyres cracking up
- Advice** Offside Rear tyre has screw in outer edge
- Advice** Nearside Rear Shock absorbers has a slightly worn bush split (5.3.2 (c))
- Fail** Offside Rear Tyre has ply or cords exposed cut in outer edge (5.2.3 (d) (ii))
- Advice** Nearside Front tyre has screw in outer edge

**MOT #10** 2020-07-27 12:02**MOT test number** 289617369917**Result** ✓ Passed**MOT #9** 2019-04-03 11:55**MOT test number** 587223822638**Result** ✓ Passed**Advice** Offside rear seat belt clasp damaged**MOT #8** 2019-04-02 09:57**MOT test number** 178206002293**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside rear seat belt clasp damaged**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2018-04-20 14:48**MOT test number** 378250701634**Result** ✓ Passed**MOT #6** 2017-04-22 09:42**MOT test number** 200140585645**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-04-23 12:29**MOT test number** 153615311677**Result** ✓ Passed**MOT #4** 2016-04-23 09:12**MOT test number** 347101850650**Result** ✗ Failed**Advice** Both rear tyres cracking on side wall**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2015-04-24 11:06**MOT test number** 925894315136**Result** ✓ Passed**Notice** Both front tyres wearing on edges and sidewalls cracking**MOT #2** 2014-04-10 11:15**MOT test number** 166100404181**Result** ✓ Passed**MOT #1** 2013-04-26 12:42**MOT test number** 719756613119**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
2 October 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-21
Last registration	2023-09-25
Complete history	See info



Registration #1	2010-04-21	8 mi
Registration #2	2013-04-26	8.262 mi
Registration #3	2014-04-10	14.183 mi
Registration #4	2015-04-24	20.157 mi
Registration #5	2016-04-23	29.466 mi
Registration #6	2016-04-23	29.466 mi
Registration #7	2017-04-22	36.579 mi
Registration #8	2018-04-20	40.688 mi
Registration #9	2019-05-20	55.577 mi
Registration #10	2019-05-20	55.577 mi
Registration #11	2019-05-20	55.577 mi
Registration #12	2019-05-20	55.577 mi
Registration #13	2019-05-20	55.577 mi
Registration #14	2019-05-20	55.577 mi
Registration #15	2019-05-20	55.577 mi
Registration #16	2019-05-20	55.577 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982525140