



HONDA



report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | HONDA |
| Model | JAZZ I-VTEC ES PLUS |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 109 mph |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 99 BHP |
| Max. torque | 127 Nm at 4.800 rpm |
| Engine capacity | 1.339 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 51.4 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-31 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-23 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 5 |

| | |
|------------------|---|
| MOT #9 | 2023-05-25 14:44 |
| MOT test number | 437811148461 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-23 |
| Advice | Manufactures engine and body covers fitted restricting inspection of components |

| | |
|-----------------|--|
| MOT #8 | 2023-05-24 11:04 |
| MOT test number | 168055703355 |
| Result | ✗ Failed |
| Advice | Manufactures engine and body covers fitted restricting inspection of components |
| Fail | Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure 185/50/16 (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #7 | 2022-06-21 12:09 |
| MOT test number | 316668001980 |
| Result | ✓ Passed |

| | |
|-----------------|---------------------------------------|
| MOT #6 | 2021-06-24 16:06 |
| MOT test number | 620256397086 |
| Result | ✓ Passed |
| Advice | All four tyres are perished 185/55/16 |

**MOT #5** 2021-06-11 16:13**MOT test number** 808590818586**Result** ✗ Failed**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** All four tyres are perished 185/55/16**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**MOT #4** 2020-11-17 16:38**MOT test number** 378143583079**Result** ✓ Passed**MOT #3** 2020-01-30 12:39**MOT test number** 418737734013**Result** ✓ Passed**MOT #2** 2019-01-31 15:30**MOT test number** 883630320063**Result** ✓ Passed**MOT #1** 2018-01-31 11:27**MOT test number** 457342332933**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
23 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 366 |
| MOT expiry date | 23 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this HONDA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | WN15PMU |
| Plate since | 2015-05-29 |
| Current registration | WN15PMU |
| Plate since | 2015-05-29 |

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-03-31 |
| Last registration | 2023-05-25 |
| Complete history | See info |



| | | |
|------------------|------------|----------|
| Registration #1 | 2015-03-31 | 23 mi |
| Registration #2 | 2018-01-31 | 2.928 mi |
| Registration #3 | 2019-01-31 | 4.384 mi |
| Registration #4 | 2020-01-30 | 5.210 mi |
| Registration #5 | 2020-11-17 | 5.455 mi |
| Registration #6 | 2020-11-17 | 5.455 mi |
| Registration #7 | 2020-11-17 | 5.455 mi |
| Registration #8 | 2020-11-17 | 5.455 mi |
| Registration #9 | 2020-11-17 | 5.455 mi |
| Registration #10 | 2020-11-17 | 5.455 mi |
| Registration #11 | 2020-11-17 | 5.455 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 78% |
| Children | 79% |
| Pedestrian | 60% |
| Safety systems | 71% |
| Overall rating | 74% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1695 mm |
| Height | 1525 mm |
| Length | 3900 mm |
| Wheel base | 2500 mm |
| Kerb weight | 1140 kg |
| Max. allowed weight | 1535 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 42 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | L13Z17209464 |