



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SEL TDI
Colour	Red
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C





MOT history

MOT expiry date	2024-04-27
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	36
Total items failed	13

MOT #16	2023-04-28 17:56
MOT test number	657142654233
Result	✓ Passed
Next expiry date	2024-04-27
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2022-04-19 13:35
MOT test number	103681507003
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2022-04-11 11:56

MOT test number

941330442866

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #13

2021-03-20 16:10

MOT test number

213311231825

Result**✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12

2021-03-20 16:10

MOT test number

734915875041

Result**✗ Failed**

- Pass with rectification** Nearside Front Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #11

2020-02-17 10:31

MOT test number

909564594779

Result**✓ Passed**

**MOT #10** 2019-02-16 12:09**MOT test number** 252703459656**Result** ✓ Passed

- Advice** Items removed from obscuring drivers vision
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9 2019-02-16 09:11**MOT test number** 965939363414**Result** ✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure wall splitting inner (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Items removed from obscuring drivers vision
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure splits on inner wall been run under inflated (5.2.3 (d) (ii))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #8 2018-02-06 09:10**MOT test number** 725116293321**Result** ✓ Passed

- Advice** Offside Front Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #7** 2017-02-06 13:50**MOT test number** 769749599027**Result** ✓ Passed

- Advice** Under trays obscuring some components
- Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front registration plate delaminated but not likely to be misread minor damage (6.3.1d)

MOT #6 2017-02-04 10:08**MOT test number** 537376267824**Result** ✗ Failed

- Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Under trays obscuring some components
- Fail** Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Front registration plate delaminated but not likely to be misread minor damage (6.3.1d)

MOT #5 2016-02-03 09:54**MOT test number** 415161531072**Result** ✓ Passed

- Advice** Engine and underbody covers fitted unable to check some components

MOT #4 2015-02-11 14:23**MOT test number** 307752845007**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2015-02-11 09:23**MOT test number** 375892945099**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-01-14 12:46**MOT test number** 917864014024**Result** ✓ Passed**Notice** Rear wiper blade rubber deteriorated**MOT #1** 2013-01-14 10:35**MOT test number** 746774613025**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 April 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	27 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-05
Last registration	2023-04-28
Complete history	See info



Registration #1	2010-01-05	14 mi
Registration #2	2013-01-14	24.826 mi
Registration #3	2014-01-14	28.530 mi
Registration #4	2015-02-11	36.208 mi
Registration #5	2015-02-11	36.208 mi
Registration #6	2016-02-03	41.143 mi
Registration #7	2017-02-04	49.183 mi
Registration #8	2017-02-06	49.236 mi
Registration #9	2018-02-06	63.018 mi
Registration #10	2019-05-29	75.377 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
-----------------	---

Engine number	CAY 041769
---------------	------------