





report date: 2024-03-28

#### General information

Make	MAZDA
Model	MX-5 ICON
Colour	White
Year of manufacture	2016
Top speed	127 mph
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	129 BHP
Max. torque	150 Nm at 4.800 rpm
Engine capacity	1.496 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

#### Entry 6

Date 2023-12-05

Pictures 0

Listing price <u>View report</u>

#### source: carcraft.co.uk

#### Entry 5

Date 2023-09-29

Pictures 4

Listing price <u>View report</u>









#### source: cargurus.co.uk

#### Entry 4

Date 2021-12-09

Pictures 31

Listing price <u>View report</u>









source: yesauto.com

#### Entry 3

Date	2021-09-23
Pictures	10
Listing price	View report

CarCheck.co.uk page 2/11









source: autoonline.co.uk

Entry 2

Date	2021-07-31
------	------------

Pictures 65

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-14
Pictures	10

Listing price <u>View report</u>









source: cargurus.co.uk



SF66WFA
report date: 2024-03-28

MOT history

MOT expiry date	2025-01-15
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	7
Total items failed	0

MOT #5	2024-01-16 14:44
MOT test number	118077946328
Result	✓ Passed
Next expiry date	2025-01-15

MOT #4	2023-04-24 11:13
MOT test number	544744318701
Result	<b>√</b> Passed

	MOT #3	2022-04-26 08:22
	MOT test	number 418856730231
1	Result	✓ Passed
	Advice	Offside Rear brake starting to bind
	Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
	Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2		2020-12-09 11:09
MOT test	number	431375917112
Result		✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT #1** 2019-12-18 09:33

**MOT test number** 101673656959

**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	15 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



#### Extra MAZDA salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_	
Owner	hictory
	HIISCOLV

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

### Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-12-20
Last registration	2024-01-16
Complete history	See info



Registration #1	2016-12-20	25 mi
Registration #2	2019-12-18	23.651 mi
Registration #3	2020-12-09	32.687 mi
Registration #4		0.777 66
Registration #5		9.77 es
Registration #6		0.777 66
Registration #7		9.77 es
Registration #8		11.777 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1735 mm
Height	1225 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	975 kg
Max. allowed weight	1215 kg

### Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	P5 30233854

CarCheck.co.uk page 11/11