



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D SPORT V50
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-12
Pictures	39
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-10-12
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	40
Total items failed	15

MOT #17 2021-10-13 16:38

MOT test number 779245932956

Result ✓ Passed

Next expiry date 2022-10-12

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16 2020-09-18 13:59

MOT test number 164945596593

Result ✓ Passed

- Advice** Lower Exhaust system corroding.

**MOT #15**

2019-06-07 14:34

MOT test number

120699329593

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Under-trays fitted
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front tyres worn on inner edges

MOT #14

2019-06-06 11:13

MOT test number

418019034749

Result

✗ Failed

- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Under-trays fitted
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front tyres worn on inner edges
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2018-06-21 11:07**MOT test number** 877081006724**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2018-06-20 13:08**MOT test number** 311290882183**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2017-03-07 14:04**MOT test number** 335545338177**Result** ✓ Passed**MOT #10** 2016-04-05 13:31**MOT test number** 417137953297**Result** ✓ Passed**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2016-04-05 09:59**MOT test number** 742985852138**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2015-03-27 14:17**MOT test number** 717206685068**Result** ✓ Passed**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Notice** Front n/s & o/s brake discs worn**MOT #7** 2015-03-26 12:55**MOT test number** 635915085035**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Notice** Front n/s & o/s brake discs worn**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #6** 2014-03-28 09:30**MOT test number** 238087984058**Result** ✓ Passed**Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-03-15 11:48**MOT test number** 347464773045**Result** ✓ Passed**MOT #4** 2013-03-15 09:36**MOT test number** 408884273066**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Indicator switch faulty (1.4.A.1)**MOT #3** 2012-03-15 15:53**MOT test number** 418115172075**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2011-03-29 15:03
MOT test number	459498281088
Result	✓ Passed
<div>Notice Front tyre treads wearing low</div>	

MOT #1	2010-03-29 10:33
MOT test number	132948180442
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 July 2022

✕
MOT

Expired:
12 October 2022

Tax status	Expired at 1 July 2022
Days left	668 days too late
MOT expiry date	12 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	GJ07VKN
Plate since	2019-03-29
Current registration	GJ07VKN
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-30
Last registration	2021-10-13
Complete history	See info



Registration #1	2007-03-30	23 mi
Registration #2	2010-03-29	36.080 mi
Registration #3	2011-03-29	47.730 mi
Registration #4	2012-03-15	61.267 mi
Registration #5	2013-03-15	68.199 mi
Registration #6	2013-03-15	68.199 mi
Registration #7	2014-03-28	75.131 mi
Registration #8	2015-03-26	86.037 mi
Registration #9	2015-03-27	86.038 mi
Registration #10	2016-04-05	93.614 mi
Registration #11	2016-04-05	93.614 mi
Registration #12	2016-04-05	93.614 mi
Registration #13	2016-04-05	93.614 mi
Registration #14	2016-04-05	93.614 mi
Registration #15	2016-04-05	93.614 mi
Registration #16	2016-04-05	93.614 mi
Registration #17	2016-04-05	93.614 mi
Registration #18	2016-04-05	93.614 mi
Registration #19	2016-04-05	93.614 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	7926
---------------	------