





report date: 2024-03-29

### General information

Make	VAUXHALL
Model	CROSSLAND ELITE NAV
Colour	Blue
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

### Entry 1


Date 2021-02-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-11-13
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #6	2023-11-06 08:44
MOT test number	730253748579
Result	✓ Passed
Next expiry date	2024-11-13

MOT #5		2022-11-14 08:45
MOT test	number	863636460169
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT #4** 2022-11-10 09:18 950344920037 **MOT** test number Result × Failed Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge bald on edge (5.2.3 (e)) Fail Exhaust has a major leak of exhaust gases flexi snapped (6.1.2 (a)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Nearside Rear Nail in tyre **Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on edge (5.2.3 (e))

MOT #3	2021-10-29 09:56
MOT test number	498904065612
Result	✓ Passed
MOT #2	2021-10-28 08:31
MOT test number	135572371776
Result	<b>X</b> Failed
Fail Front Exhaust system insecure (6.1.2 (a))	

MOT #1	2020-10-19 15:13
MOT test number	211778609234
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

### Tax & MOT check



**MOT** 

Tax status	Valid until 1 August
Days left	95
MOT expiry date	13 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

#### Damage 1

**Date Category Type** Damage 2

Category

**Type** 

**Date** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.		
********		
***************************************		
*********		
************		
	More info >	
Plate changes		
See in this check if this VAUXHALL had different number plates.		
Number of plates		,
Current registration	NK NE	
Plate since		
Current registration	UK UK	
Plate since		

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-02-27
Last registration	2023-11-06
Complete history	See info



Registration #1	2018-02-27	16 mi
Registration #2	2020-10-19	7.245 mi
Registration #3		9.777 es
Registration #4	2021-10-28	11.226 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	85%
Children	84%
Pedestrian	62%
Safety systems	57%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	1976 mm
Height	1597 mm
Length	4212 mm
Wheel base	2604 mm
Kerb weight	1099 kg
Max. allowed weight	1690 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	10XVDA0035991 LEZ

CarCheck.co.uk page 11/11