



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Black
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	149 g/km
CO2 label	F



**MOT history**

MOT expiry date	2024-05-19
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	8
Total items failed	11

MOT #16	2023-05-20 10:27
MOT test number	362367494000
Result	✓ Passed
Next expiry date	2024-05-19

MOT #15	2021-09-06 13:30
MOT test number	522717800921
Result	✓ Passed

MOT #14	2019-09-30 09:34
MOT test number	131618634407
Result	✓ Passed

MOT #13	2019-09-27 17:19
MOT test number	324377791535
Result	✗ Failed
Fail	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

MOT #12	2018-08-09 15:26
MOT test number	514988594227
Result	✓ Passed

**MOT #11**

2018-08-09 08:12

**MOT test number**

669248764299

**Result****✗ Failed**

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**MOT #10**

2017-09-07 12:16

**MOT test number**

473748572045

**Result****✓ Passed****MOT #9**

2017-09-07 08:04

**MOT test number**

647352787883

**Result****✗ Failed**

**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)

**MOT #8**

2016-08-09 15:52

**MOT test number**

310690775824

**Result****✓ Passed**

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2016-08-09 09:54**MOT test number** 955564163730**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front bearing slightly rough**Fail** Exhaust has a major leak of exhaust gases flexi (7.1.2)**Fail** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2015-08-04 16:23**MOT test number** 549946615269**Result** ✓ Passed**MOT #5** 2015-07-31 11:02**MOT test number** 638522815268**Result** ✗ Failed**Fail** Nearside rear brake excessively fluctuating (3.7.B.3)**MOT #4** 2014-08-22 09:27**MOT test number** 729864134235**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2013-08-07 08:56**MOT test number** 295789113221**Result** ✓ Passed



MOT #2	2012-08-30 15:41
MOT test number	855863642274
Result	✓ Passed

MOT #1	2012-08-29 16:53
MOT test number	306302642297
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
19 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	19 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-02
Last registration	2023-05-20
Complete history	<a href="#">See info</a>



Registration #1	2009-09-02	21 mi
Registration #2	2012-08-29	22.846 mi
Registration #3	2012-08-30	22.846 mi
Registration #4	2013-08-07	31.168 mi
Registration #5	2014-08-22	41.433 mi
Registration #6	2015-07-31	50.355 mi
Registration #7	2015-08-04	50.447 mi
Registration #8	2016-08-09	59.559 mi
Registration #9	2016-08-09	59.559 mi
Registration #10	2016-08-09	59.559 mi
Registration #11	2016-08-09	59.559 mi
Registration #12	2016-08-09	59.559 mi
Registration #13	2016-08-09	59.559 mi
Registration #14	2016-08-09	59.559 mi
Registration #15	2016-08-09	59.559 mi
Registration #16	2016-08-09	59.559 mi
Registration #17	2016-08-09	59.559 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG 116680