



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Black
Year of manufacture	-
Top speed	72 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-03
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #22	2022-09-30 14:44
MOT test number	159325788228
Result	✓ Passed
Next expiry date	2023-09-29
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #21	2022-09-29 09:01
MOT test number	392324334012
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Driver's seat insecure (6.2.5 (a) (ii))
Fail	Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #20	2021-04-13 14:48
MOT test number	688220487858
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2021-04-13 14:48

MOT test number

949708400618

Result**✗ Failed****Pass with rectification** Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #18**

2020-06-06 10:09

MOT test number

713782259277

Result**✓ Passed****Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Steering wheel slightly worn**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Drivers seat slightly insecure**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Parking brake requirements just met**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17**

2019-06-07 11:10

MOT test number

502586604688

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.0 mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.0 mm (5.2.3 (e))

**MOT #16** 2019-06-07 11:10**MOT test number** 904553350398**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.0 mm (5.2.3 (e))**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.0 mm (5.2.3 (e))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #15** 2018-02-03 11:25**MOT test number** 131806607976**Result** ✓ Passed**MOT #14** 2018-01-16 15:11**MOT test number** 165080998491**Result** ✗ Failed**Fail** Nearside Front Headlamp aim not tested not installed correctly (1.8.A.1c)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Front registration plate letter/figure incomplete (6.3.1c)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Direction indicator not working wing mirror indicator (1.4.A.2c)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Wheel nut(s) missing each wheel one missing (4.2.A.1e)**MOT #13** 2016-09-24 10:55**MOT test number** 452892864112**Result** ✓ Passed

**MOT #12** 2015-11-02 14:59**MOT test number** 527660689007**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit Inner edge. (4.1.E.1)

MOT #11 2015-11-02 14:42**MOT test number** 914225546280**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit Inner edge. (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Front Tyre tread depth below requirements of 1.6mm Both (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #10 2014-10-09 11:43**MOT test number** 609592584257**Result** ✓ Passed

- Notice** Nail in nearside rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in offside rear tyre
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #9** 2014-10-09 11:43**MOT test number** 707902584237**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Nail in offside rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Nail in nearside rear tyre
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components

MOT #8 2013-11-23 12:43**MOT test number** 126517923381**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2012-10-27 09:35**MOT test number** 968351402323**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2011-10-31 15:21**MOT test number** 659194801357**Result** ✓ Passed

**MOT #5** 2011-05-05 15:35**MOT test number** 219705321435**Result** ✓ Passed**MOT #4** 2010-11-12 10:15**MOT test number** 370086310381**Result** ✓ Passed**MOT #3** 2010-11-08 13:28**MOT test number** 762722110381**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Mearside rear brake disc scored, all brake pads appear to be worn very low**Fail** Offside Front Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)**MOT #2** 2010-05-18 16:10**MOT test number** 723008230148**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-11-17 15:16**MOT test number** 111701229343**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LT58PNY
Plate since	2019-03-28
Current registration	LT58PNY
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-11-10
Last registration	2022-09-30
Complete history	See info



Registration #1	2008-11-10	26 mi
Registration #2	2009-11-17	23.698 mi
Registration #3	2010-05-18	36.806 mi
Registration #4	2010-11-08	51.202 mi
Registration #5	2010-11-12	51.233 mi
Registration #6	2011-05-05	65.167 mi
Registration #7	2011-10-31	76.926 mi
Registration #8	2012-10-27	96.632 mi
Registration #9	2013-11-23	107.484 mi
Registration #10	2014-10-09	113.923 mi
Registration #11	2015-11-02	119.894 mi
Registration #12	2015-11-02	119.894 mi
Registration #13	2016-05-20	121.277 mi
Registration #14	2016-05-20	121.277 mi
Registration #15	2016-05-20	121.277 mi
Registration #16	2016-05-20	121.277 mi
Registration #17	2016-05-20	121.277 mi
Registration #18	2016-05-20	121.277 mi
Registration #19	2016-05-20	121.277 mi
Registration #20	2016-05-20	121.277 mi
Registration #21	2016-05-20	121.277 mi
Registration #22	2016-05-20	121.277 mi
Registration #23	2016-05-20	121.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

8R41849