





report date: 2024-03-28

#### General information

| Make                | VOLVO             |
|---------------------|-------------------|
| Model               | S90 D4 MOMENTUM   |
| Colour              | Grey              |
| Year of manufacture | 2018              |
| Top speed           | 140 mph           |
| 0 - 60 mph          | 7.9 seconds       |
| Gearbox             | 8 speed automatic |

### Engine & fuel consumption

| Power                   | 190 BHP             |
|-------------------------|---------------------|
| Max. torque             | 400 Nm at 2.500 rpm |
| Engine capacity         | 1.969 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 53.3 mpg            |
| Consumption extra urban | 72.4 mpg            |
| Consumption combined    | 64.2 mpg            |
| CO2 emission            | 116 g/km            |
| CO2 label               | С                   |



CarCheck.co.uk page 1/10



LO18LHK

report date: 2024-03-28

### Internet history

#### Entry 1


Date 2021-07-02

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date    | 2024-06-25 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 6          |
| Total items failed | 0          |

| MOT #3           | 2023-06-26 15:43 |
|------------------|------------------|
| MOT test number  | 638729516548     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2024-06-25       |

| MOT #2   |  | 2022-05-30 08:29 |
|----------|--|------------------|
| MOT test | number   | 202834827493     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                   |                  |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                 |                  |
| Advice   | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                  |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice   | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                  |                  |

| MOT #1          | 2021-06-15 14:01 |
|-----------------|------------------|
| MOT test number | 571437550377     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/10



#### Tax & MOT check



| Tax status       | Valid until 1 October |
|------------------|-----------------------|
| Days left        | 155                   |
| MOT expiry date  | 25 June 2024          |
| Full MOT history | See MOT history       |

#### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | G          |
| First licence fee (12 months)                        | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/10



LO18LHK

report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| Owner history  |           |   |
|--|-----------|---|
| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.  |           | ) |
| THE PARTY OF THE P |           |   |
| ***************************************  |           |   |
| ***************************************  |           |   |
| ********   |           |   |
|  |           |   |
| ***************************************  |           |   |
|  | More info | > |
| Plate changes  |           |   |
| See in this check if this VOLVO had different number plates.   |           |   |
| Number of plates   |           | 9 |
| Current registration   | UK UK     |   |
| Plate since  |           |   |
| Current registration   | UK UK     |   |
| Plate since  |           |   |
|  | More info | > |
|  |           |   |

CarCheck.co.uk page 7/10



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 8/10



## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2018-07-23 |
| Last registration          | 2023-06-26 |
| Complete history           | See info   |



| Registration #1 | 2018-07-23 | 8 mi      |
|-----------------|------------|-----------|
| Registration #2 | 2021-06-15 | 21.219 mi |
| Registration #3 |            | 11.177 es |
| Registration #4 |            | 71.777 es |
| Registration #5 |            | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 95%             |
| Children       | 80%             |
| Pedestrian     | 76%             |
| Safety systems | 93%             |
| Overall rating | 88%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 2019 mm |
|---------------------|---------|
| Height              | 1443 mm |
| Length              | 4963 mm |
| Wheel base          | 2941 mm |
| Kerb weight         | 1680 kg |
| Max. allowed weight | 2270 kg |

# Additional information

| Fuel tank capacity                | 55 I             |            |
|-----------------------------------|------------------|------------|
| Fuel delivery                     | Direct Injection |            |
| Number of doors                   | 4                |            |
| Number of seats<br>CarCheck.co.uk | 5                | page 10/10 |