



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 350
Colour	Silver
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 5.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	36.2 mpg
Consumption combined	28.0 mpg
CO2 emission	242 g/km
CO2 label	L





Internet history

Entry 4

Date	2023-03-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 3


Date	2023-03-29
Pictures	1
Listing price	View report



source: autotrader.co.uk

Entry 2

Date	2022-08-20
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-20
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-06
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	19
Total items failed	9

MOT #21	2023-06-07 12:14
MOT test number	340511583493
Result	✓ Passed
Next expiry date	2024-06-06

MOT #20	2022-09-23 12:32
MOT test number	727659859536
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2022-09-23 11:49
MOT test number	459830128730
Result	✗ Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #18** 2021-09-13 18:03**MOT test number** 502331679732**Result** ✓ Passed**MOT #17** 2021-07-16 15:06**MOT test number** 968045320887**Result** ✓ Passed**MOT #16** 2021-07-07 14:58**MOT test number** 670500174949**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken broken at bottom. (5.3.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #15** 2020-07-06 08:52**MOT test number** 771712060544**Result** ✓ Passed**MOT #14** 2019-08-17 13:14**MOT test number** 461916433883**Result** ✓ Passed**MOT #13** 2018-08-21 11:47**MOT test number** 928116664962**Result** ✓ Passed

**MOT #12** 2018-08-16 14:16**MOT test number** 528864484256**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2018-03-03 20:29**MOT test number** 793607854340**Result** ✓ Passed**MOT #10** 2018-03-03 15:44**MOT test number** 512847274590**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2017-03-02 13:29**MOT test number** 495241108666**Result** ✓ Passed**Advice** Offside Rear tyre outer side wall damage.**Advice** Offside Rear Nail in tyre**MOT #8** 2016-02-17 13:01**MOT test number** 667997539124**Result** ✓ Passed**Advice** Tyre worn close to the legal limit both rears (4.1.E.1)**MOT #7** 2015-03-04 16:36**MOT test number** 838113165080**Result** ✓ Passed

**MOT #6** 2015-03-03 14:40**MOT test number** 549022365082**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #5** 2014-02-27 12:30**MOT test number** 196708854057**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Front tyres wearing on edges**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2013-02-08 15:03**MOT test number** 907199233009**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-02-17 16:30**MOT test number** 796988242047**Result** ✓ Passed**Notice** Unable to fully check fuel and brake pipes shields fitted**MOT #2** 2012-02-17 13:05**MOT test number** 827258042097**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Unable to fully check fuel and brake pipes shields fitted**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #1

2011-03-15 11:24

MOT test number

167654571453

Result

✓ Passed

- Notice

Front and Rear Brake discs corroding
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
6 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 YX1234
Plate since	2019-01-01
Current registration	 YX1234
Plate since	2019-01-01

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-27
Last registration	2023-06-07
Complete history	See info



Registration #1	2007-09-27	26 mi
Registration #2	2011-03-15	32.398 mi
Registration #3	2012-02-17	36.600 mi
Registration #4	2012-02-17	36.612 mi
Registration #5	2013-02-08	40.233 mi
Registration #6	2014-02-27	43.686 mi
Registration #7	2015-03-03	48.713 mi
Registration #8	2015-03-04	48.713 mi
Registration #9	2016-02-17	52.630 mi
Registration #10	2017-03-02	64.420 mi
Registration #11	2018-03-03	77.842 mi
Registration #12	2018-03-03	77.842 mi
Registration #13	2018-08-16	81.502 mi
Registration #14	2019-05-20	85.377 mi
Registration #15	2019-05-20	85.377 mi
Registration #16	2019-05-20	85.377 mi
Registration #17	2019-05-20	85.377 mi
Registration #18	2019-05-20	85.377 mi
Registration #19	2019-05-20	85.377 mi
Registration #20	2019-05-20	85.377 mi
Registration #21	2019-05-20	85.377 mi
Registration #22	2019-05-20	85.377 mi
Registration #23	2019-05-20	85.377 mi
Registration #24	2019-05-20	85.377 mi
Registration #25	2019-05-20	85.377 mi
Registration #26	2019-05-20	85.377 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296330596135