



report date: 2024-03-28

General information

Make	SMART
Model	FORTWO COUPE PASSION 71
Colour	Black
Year of manufacture	2008
Top speed	90 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	13.3 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 2


Date	2021-09-25
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-07
Pictures	6
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-09-07
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	22
Total items failed	1

MOT #15	2023-08-30 15:27
MOT test number	125017764139
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14	2022-09-08 10:18
MOT test number	129529268569
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking / perishing (5.2.3 (d) (ii))
Advice	Stop lamp(s) non-obligatory stop lamp not working high level 100% inop (4.3.1 (a) (ii))
Advice	Fuel cap/sealing device- rubber seal poor splitting
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2021-09-06 17:57
MOT test number	690898796695
Result	✓ Passed

**MOT #12** 2021-08-28 07:31**MOT test number** 550130334486**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-10-07 12:37**MOT test number** 510678912108**Result** ✓ Passed**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #10** 2020-10-06 13:58**MOT test number** 946346636195**Result** ✗ Failed**MAJOR** Windscreen washer not working (3.5 (a))**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Windscreen in an unacceptable condition (3.2 (c) (i))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #9** 2019-04-03 14:43**MOT test number** 750011952390**Result** ✓ Passed

**MOT #8** 2019-04-03 10:40**MOT test number** 919944295114**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 3 mm (5.2.3 (e))**MOT #7** 2016-08-31 15:04**MOT test number** 304972325395**Result** ✓ Passed**MOT #6** 2016-05-25 10:42**MOT test number** 315339752383**Result** ✓ Passed**MOT #5** 2015-07-08 13:00**MOT test number** 557889885179**Result** ✓ Passed**MOT #4** 2014-07-10 12:38**MOT test number** 289611994162**Result** ✓ Passed**MOT #3** 2014-07-10 11:07**MOT test number** 876341894169**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #2	2013-07-04 12:13
MOT test number	539005983192
Result	✓ Passed

MOT #1	2012-07-04 14:44
MOT test number	845166982184
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-27
Last registration	2023-08-30
Complete history	See info



Registration #1	2008-09-27	19 mi
Registration #2	2012-07-04	8.669 mi
Registration #3	2013-07-04	24.911 mi
Registration #4	2014-07-10	12.278 mi
Registration #5	2014-07-10	12.278 mi
Registration #6	2015-07-08	15.335 mi
Registration #7	2016-05-25	18.614 mi
Registration #8	2016-08-31	19.401 mi
Registration #9	2019-04-03	28.160 mi
Registration #10	2019-04-03	28.160 mi
Registration #11	2019-04-03	28.160 mi
Registration #12	2019-04-03	28.160 mi
Registration #13	2019-04-03	28.160 mi
Registration #14	2019-04-03	28.160 mi
Registration #15	2019-04-03	28.160 mi
Registration #16	2019-04-03	28.160 mi
Registration #17	2019-04-03	28.160 mi
Registration #18	2019-04-03	28.160 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139