



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO VISIA
Colour	White
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-06-06
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-11
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	15
Total items failed	7

MOT #14	2023-10-11 15:41
MOT test number	839618119657
Result	✓ Passed
Next expiry date	2024-10-11

MOT #13	2023-10-09 12:59
MOT test number	276828752878
Result	✗ Failed
Fail	Offside Rear Suspension arm likely to become detached fractured due to a corrosion (5.3.3 (a) (ii))

MOT #12	2022-09-22 10:46
MOT test number	642948747755
Result	✓ Passed
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #11	2022-09-22 10:46
MOT test number	492201985668
Result	✗ Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively both damaged (3.4 (b) (ii))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2021-10-04 10:39**MOT test number** 596271299765**Result** ✓ Passed**MOT #9** 2020-10-12 15:53**MOT test number** 362239771176**Result** ✓ Passed**MOT #8** 2020-10-12 10:24**MOT test number** 213764090730**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2019-06-29 07:11**MOT test number** 202718079592**Result** ✓ Passed**MOT #6** 2019-06-29 07:11**MOT test number** 875743334509**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm replace (5.2.3 (e))

**MOT #5** 2018-05-12 12:06**MOT test number** 992792632010**Result** ✓ Passed**MOT #4** 2017-07-17 13:47**MOT test number** 849468268885**Result** ✓ Passed**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Outer tyre wall damaged.**Advice** Front number plate damaged.**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Outer tyre wall perished.**MOT #3** 2016-06-20 13:15**MOT test number** 535291400537**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit splitting in tread. (4.1.E.1)**Advice** Front number plate damaged.**Advice** Offside Front Tyre worn close to the legal limit slitting in tread and outer wall. (4.1.E.1)**MOT #2** 2015-06-25 09:20**MOT test number** 716476175145**Result** ✓ Passed**MOT #1** 2014-07-08 15:12**MOT test number** 717079884171**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
11 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	11 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	NG11ERX
Plate since	2019-03-28
Current registration	NG11ERX
Plate since	2019-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-07-15
Last registration	2023-10-11
Complete history	See info



Registration #1	2011-07-15	21 mi
Registration #2	2014-07-08	5.335 mi
Registration #3	2015-06-25	6.911 mi
Registration #4	2016-06-20	8.428 mi
Registration #5	2017-07-17	9.770 mi
Registration #6	2018-05-12	10.393 mi
Registration #7	2019-06-29	22.369 mi
Registration #8	2019-06-29	22.369 mi
Registration #9	2019-06-29	22.369 mi
Registration #10	2019-06-29	22.369 mi
Registration #11	2019-06-29	22.369 mi
Registration #12	2019-06-29	22.369 mi
Registration #13	2019-06-29	22.369 mi
Registration #14	2019-06-29	22.369 mi
Registration #15	2019-06-29	22.369 mi
Registration #16	2019-06-29	22.369 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133813