



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	CL CL63 AMG
Colour	Silver
Year of manufacture	2007
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	518 BHP
Max. torque	630 Nm at 5.200 rpm
Engine capacity	6.209 cc
Cylinders	8
Fuel type	Petrol
Consumption city	12.2 mpg
Consumption extra urban	27.7 mpg
Consumption combined	19.0 mpg
CO2 emission	355 g/km
CO2 label	M






Internet history

Entry 2


Date	2021-09-10
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-02
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-01-17
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	48
Total items failed	8

MOT #17 2021-09-30 08:26

MOT test number 246917920011

Result ✓ Passed

Next expiry date 2022-09-29

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16 2021-01-11 12:58

MOT test number 942567991002

Result ✓ Passed

- Advice** Nearside Front Inner Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** The dust cover on the n/s/r damper is perished

**MOT #15** 2020-01-14 13:47**MOT test number** 518753673472**Result** ✓ Passed**MOT #14** 2019-07-24 07:43**MOT test number** 685101712696**Result** ✓ Passed**Advice** Both front fog lamps lens slight damage**Advice** Suspension arm ball joint has slight play front lower ball joints slight play (5.3.4 (a) (i))**MOT #13** 2018-07-27 10:50**MOT test number** 170928567355**Result** ✓ Passed**Advice** Front tyres edges slightly worn**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower fog lamp lens slightly damaged**MOT #12** 2017-08-04 08:53**MOT test number** 482337853038**Result** ✓ Passed**Advice** Undertrays fitted obscuring some underside components**Advice** Front offside lower ball joint slight play**Advice** Windscreen slightly damaged**Advice** Front offside lower fog lamp lens slight damage



MOT #11 2016-08-10 13:33

MOT test number 283860806577

Result ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both on inner surface (3.5.1i)

Advice Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Offside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

MOT #10 2015-07-24 11:59

MOT test number 519805805203

Result ✓ Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Offside front fog lamp cracked

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Offside front side repeater cracked

**MOT #9**

2014-08-06 14:03

MOT test number

776578214263

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Notice** O/S/F fog lamp lens cracked
- Notice** Both front tyres wearing on edges, worse on inner edges
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** O/S/R tyre valve starting to perish slightly
- Notice** SLight buckle on both front wheel inner rims

MOT #8

2014-08-06 14:03

MOT test number

657578414252

Result

✗ Failed

- Notice** Both front tyres wearing on edges, worse on inner edges
- Pass with rectification** Nearside Front Headlamp aim too low (1.8)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/S/R tyre valve starting to perish slightly
- Notice** SLight buckle on both front wheel inner rims
- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Notice** O/S/F fog lamp lens cracked

**MOT #7** 2013-08-07 12:27**MOT test number** 419329113229**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2012-08-10 12:37**MOT test number** 758233722283**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2012-08-10 11:55**MOT test number** 138143022208**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-09-02 16:23**MOT test number** 976875241232**Result** ✓ Passed



MOT #3	2011-09-02 11:07
MOT test number	425935241236
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Headlamp aim too high (1.8)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Parking brake: efficiency below requirements (3.7.B.7)

MOT #2	2010-09-14 17:12
MOT test number	522927650200
Result	✓ Passed
MOT #1	2010-03-25 16:08
MOT test number	642364280078
Result	✓ Passed
Notice	Under floor covers fitted



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
17 January 2024

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	17 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2023-03-29
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-28
Last registration	2021-09-30
Complete history	See info



Registration #1	2007-03-28	24 mi
Registration #2	2010-03-25	20.672 mi
Registration #3	2010-09-14	22.370 mi
Registration #4	2011-09-02	27.767 mi
Registration #5	2011-09-02	27.767 mi
Registration #6	2012-08-10	37.019 mi
Registration #7	2012-08-10	37.019 mi
Registration #8	2013-08-07	40.528 mi
Registration #9	2014-08-06	47.665 mi
Registration #10	2015-07-24	52.920 mi
Registration #11	2016-06-20	55.377 mi
Registration #12	2016-06-20	55.377 mi
Registration #13	2016-06-20	55.377 mi
Registration #14	2016-06-20	55.377 mi
Registration #15	2016-06-20	55.377 mi
Registration #16	2016-06-20	55.377 mi
Registration #17	2016-06-20	55.377 mi
Registration #18	2016-06-20	55.377 mi
Registration #19	2016-06-20	55.377 mi

More info >



Dimensions & weight

Width	1871 mm
Height	1418 mm
Length	5084 mm
Wheel base	2955 mm
Kerb weight	2085 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	15698460011648