





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Purple
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-14

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-24
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	26
Total items failed	6

MOT #10		2023-07-25 12:45
MOT test	number	708160011576
Result		✓ Passed
Next expi	ry date	2024-07-24
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c	:))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))

MOT #	9	2023-07-25 11:01
MOT te	est number	322539915450
Result		× Failed
Advi	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Front Tyre tread depth below requirements of 1.6mm offside & nearside (5.2.3 (e))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advi	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advi	Brake pipe corroded, covered in grease or other material front to rears (1.1.11 ((c))

CarCheck.co.uk page 3/12



Result

MT62YSV

report date: 2024-03-28

✓ Passed

MOT #8 2022-07-08 10:51

MOT test number 156526274875

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Items on rear seats not allowing inspection on all rear seat belts

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge of tyre (5.2.3 (e))

MOT #7 2022-07-08 10:51

MOT test number 843536128925

Result × Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))

Items on rear seats not allowing inspection on all rear seat belts Advice

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge of tyre (5.2.3 (e))

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/12



MOT #2

MT62YSV

report date: 2024-03-28

MOT #6

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Inner edges (1.1.14 (a) (ii))

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4	2019-02-11 10:59
MOT test number	769536589532
Result	✓ Passed

MO1 #3	2010-07-23 09.27
MOT test number	383787441621
Result	✓ Passed

MOT #2	2017-06-01 12:44
MOT test number	414751417950
Result	✓ Passed

MOT #1	2016-06-10 08:31
MOT test number	443726461021
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
See in this check if this i 20020 i had amerene hamber plates.	
Mumber of plates	
	NIE.
Correct registration	UK NAME OF THE PROPERTY OF THE
Plate since	
Current registration	OK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-01-19
Last registration	2023-07-25
Complete history	See info



Registration #1	2013-01-19	26 mi
Registration #2	2016-06-10	34.281 mi
Registration #3	2017-06-01	41.985 mi
Registration #4	2018-07-23	45.703 mi
Registration #5	2019-02-11	45.818 mi
Registration #6	2020-01-22	53.931 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12