



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Red
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-19
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	33
Total items failed	10

MOT #17	2023-05-10 15:20
MOT test number	703429354960
Result	✓ Passed
Next expiry date	2024-05-09
Advice	General under body surface rust front to back

MOT #16	2022-04-09 11:45
MOT test number	683693588811
Result	✓ Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15	2022-04-09 11:45
MOT test number	872369589876
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14	2021-03-12 10:44
MOT test number	286945674872
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2020-03-17 13:41

MOT test number

683013811672

Result

✓ Passed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2020-03-14 14:59

MOT test number

208599124240

Result

✗ Failed

Fail

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2019-03-30 14:00

MOT test number

303563317348

Result

✓ Passed

Advice

Coil spring corroded front and rear all four (5.3.1 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice

Front Anti-roll bar ball joint has slight play both sides (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2018-03-23 13:02

MOT test number

950446052911

Result

✓ Passed

Advice

Rear coil spring corroded Both sides (2.4.C.1b)

**MOT #9** 2017-04-08 15:41**MOT test number** 835313387252**Result** ✓ Passed**MOT #8** 2016-03-21 11:23**MOT test number** 946165686243**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Steering system has slight free play detected at steering wheel both steering arms (2.2.A.1b)

MOT #7 2016-03-20 12:48**MOT test number** 936439979849**Result** ✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Exhaust system not adequately supported rear exhaust mount broken (7.1.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Headlamp not working on dipped beam aim not tested (1.7.5a)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Steering system has slight free play detected at steering wheel both steering arms (2.2.A.1b)

**MOT #6** 2015-03-24 17:17**MOT test number** 657243585049**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Oil leak**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Nail in offside rear tyre**MOT #5** 2015-03-22 10:57**MOT test number** 145591685451**Result** ✗ Failed**Fail** Steering wheel locking device insecure (2.1.6)**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**Notice** Oil leak**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Notice** Nail in offside rear tyre**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2013-10-26 16:31**MOT test number** 656289893226**Result** ✓ Passed**Notice** O/s/r tyre worn on inner edge**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #3	2012-10-23 14:11
MOT test number	426767892258
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Front exhaust section is deteriorated

MOT #2	2011-10-24 14:54
MOT test number	306377591449
Result	✓ Passed
Advice	Steering column top bearing slightly worn (2.1.2c)

MOT #1	2011-05-04 12:33
MOT test number	939614721116
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 May 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YS08GKK
Plate since	2024-03-29
Current registration	 YS08GKK
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-17
Last registration	2023-05-10
Complete history	See info



Registration #1	2008-06-17	17 mi
Registration #2	2011-05-04	14.608 mi
Registration #3	2011-10-24	15.262 mi
Registration #4	2012-10-23	20.986 mi
Registration #5	2013-10-26	29.900 mi
Registration #6	2015-03-22	39.437 mi
Registration #7	2015-03-24	39.449 mi
Registration #8	2016-03-20	46.152 mi
Registration #9	2016-03-21	46.152 mi
Registration #10	2017-04-08	53.302 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi
Registration #16	2019-05-20	55.377 mi
Registration #17	2019-05-20	55.377 mi
Registration #18	2019-05-20	55.377 mi
Registration #19	2019-05-20	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564