



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 SE SE BLUE DRIVE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	134 Nm at 3.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-28
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #8 2023-10-23 11:33

MOT test number 877645451399

Result ✓ Passed

Next expiry date 2024-10-26

- Advice** Front Brake disc worn, but not excessively BOTH (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm + worn inner (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Minor** Windscreen wiper blade defective slight smearing (3.4 (b) (i))

MOT #7 2022-10-25 09:19

MOT test number 760977972260

Result ✓ Passed

MOT #6 2021-10-27 11:43

MOT test number 608754572482

Result ✓ Passed

MOT #5 2021-10-27 11:43

MOT test number 505200803052

Result ✗ Failed

- Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #4**

2020-07-31 12:58

MOT test number

663719342210

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive Engine. (8.4.1 (a) (i))

MOT #3

2020-07-31 08:48

MOT test number

737349629736

Result

✗ Failed

- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Fail** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive Engine. (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #2	2019-08-01 12:15
MOT test number	335453973031
Result	✓ Passed
MOT #1	2018-08-21 13:16
MOT test number	893377670044
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
26 October 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-30
Last registration	2023-10-23
Complete history	See info



Registration #1	2015-09-30	8 mi
Registration #2	2018-08-21	46.389 mi
Registration #3	2019-08-01	53.339 mi
Registration #4	2020-07-31	59.309 mi
Registration #5	2020-07-31	59.309 mi
Registration #6	2020-07-31	59.309 mi
Registration #7	2020-07-31	59.309 mi
Registration #8	2020-07-31	59.309 mi
Registration #9	2020-07-31	59.309 mi
Registration #10	2020-07-31	59.309 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1314 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LCFZ016652