



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SE TDI
Colour	Black
Year of manufacture	2009
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F





## Internet history

### Entry 3

Date	2022-06-24
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 2

Date	2021-06-25
Pictures	17
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 1

Date	2021-06-24
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-03-13
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	38
Total items failed	10

MOT #17	2024-02-27 14:38
MOT test number	592487734203
Result	✓ Passed
Next expiry date	2025-03-13
Advice	Surface corrosion to rear suspension components

MOT #16	2023-03-06 12:22
MOT test number	143326274985
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Covers fitted
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Surface corrosion to rear suspension components

MOT #15	2022-03-14 08:34
MOT test number	946027717201
Result	✓ Passed

**MOT #14** 2022-03-09 17:20**MOT test number** 297043798195**Result** ✗ Failed**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #13** 2021-06-10 16:19**MOT test number** 232828986015**Result** ✓ Passed**MOT #12** 2020-07-23 14:02**MOT test number** 951048784767**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2020-07-23 09:56**MOT test number** 775089566506**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #10** 2019-08-03 10:41**MOT test number** 363335138694**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge 235/45/17 (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge 235/45/17 (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Tracking is out**Advice** Offside Rear Outer Nail in tyre 235/45/17**MOT #9** 2018-07-09 09:00**MOT test number** 521983472256**Result** ✓ Passed**Advice** Emission pass, 0.04, temp probe used**MOT #8** 2018-07-09 07:47**MOT test number** 693419725352**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Emission pass, 0.04, temp probe used**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #7** 2017-07-12 09:40**MOT test number** 198737565342**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 235/45/17 (4.1.E.1)
- Advice** Offside Rear Inner Tyre worn close to the legal limit 235/45/17 (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit 235/45/17 (4.1.E.1)
- Advice** Nearside Rear Inner Tyre worn close to the legal limit 235/45/17 (4.1.E.1)
- Advice** Diesel emissions passed, 0.00K T/C, oil temp probe was used

**MOT #6** 2016-07-18 08:16**MOT test number** 802852259634**Result** ✓ Passed

- Advice** Engine covers are fitted top & bottom
- Advice** Diesel emissions passed,0.00K T/C

**MOT #5** 2015-07-20 08:46**MOT test number** 826261605299**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Diesel emissions passed,0.00K T/C
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #4** 2014-07-21 08:41**MOT test number** 319752104288**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Diesel emissions passed,0.00k T/C**MOT #3** 2013-06-27 14:33**MOT test number** 306048873133**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-06-25 09:45**MOT test number** 357756273111**Result** ✗ Failed**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)



MOT #1	2012-07-26 10:17
MOT test number	346728802291
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Advise condition of front brake discs
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
13 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	13 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>RK59THZ</b>
Plate since	2019-06-29
Current registration	<b>RK59THZ</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-03
Last registration	2024-02-27
Complete history	<a href="#">See info</a>



Registration #1	2009-09-03	10 mi
Registration #2	2012-07-26	26.480 mi
Registration #3	2013-06-25	37.179 mi
Registration #4	2013-06-27	37.185 mi
Registration #5	2014-07-21	46.389 mi
Registration #6	2015-07-20	55.834 mi
Registration #7	2016-07-18	64.241 mi
Registration #8	2017-07-12	73.405 mi
Registration #9	2018-07-09	82.915 mi
Registration #10	2018-07-09	82.915 mi
Registration #11	2019-08-03	92.370 mi
Registration #12	2020-08-03	101.825 mi
Registration #13	2021-08-03	111.280 mi
Registration #14	2022-08-03	120.735 mi
Registration #15	2023-08-03	130.190 mi
Registration #16	2024-02-27	139.645 mi
Registration #17		
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1552 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBA 601959