



report date: 2024-03-29

General information

Make	NISSAN
Model	PULSAR N-CONNECTA DCI
Colour	Red
Year of manufacture	2016
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A






Internet history

Entry 2


Date	2021-09-30
Pictures	33
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-18
Pictures	33
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-30
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	11
Total items failed	6

MOT #8	2023-09-11 17:13
MOT test number	819806534853
Result	✓ Passed
Next expiry date	2024-09-30
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Advice	Handbrake adjustment required
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2023-09-11 10:01**MOT test number** 209999617176**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Handbrake adjustment required**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Fail** Horn not working (7.7 (a))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2022-09-08 14:13**MOT test number** 308123713635**Result** ✓ Passed**MOT #5** 2022-09-08 11:13**MOT test number** 497131746851**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**MOT #4** 2021-10-01 11:21**MOT test number** 218116877520**Result** ✓ Passed**Advice** Rear both tyres slightly perished



MOT #3	2020-11-06 12:44
MOT test number	470816867452
Result	✓ Passed

MOT #2	2020-11-05 09:26
MOT test number	798502772421
Result	✗ Failed
<div><div>Fail</div> Nearside Front Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))</div> <div><div>Fail</div> Offside Front Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))</div>	

MOT #1	2019-10-17 09:12
MOT test number	414442338782
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
30 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	30 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-11-14
Last registration	2023-09-11
Complete history	<a href="#">See info</a>



Registration #1	2016-11-14	14 mi
Registration #2	2019-10-17	60.208 mi
Registration #3	2020-11-05	73.544 mi
Registration #4	2020-11-06	73.548 mi
Registration #5	2020-11-06	73.548 mi
Registration #6	2020-11-06	73.548 mi
Registration #7	2020-11-06	73.548 mi
Registration #8	2020-11-06	73.548 mi
Registration #9	2020-11-06	73.548 mi
Registration #10	2020-11-06	73.548 mi
Registration #11	2020-11-06	73.548 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1768 mm
Height	1520 mm
Length	4387 mm
Wheel base	2700 mm
Kerb weight	1353 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	316443D