



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Grey
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	138 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-07-19
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-30
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	60
Total items failed	18

MOT #23	2023-10-31 07:57
MOT test number	628883821831
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))
Advice	Nearside HEADLAMP BEAM PATTERN POOR
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	EXHAUST PIPE MISSING TAIL END
Advice	Offside Rear Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #22**

2023-10-30 10:35

MOT test number

668186141876

Result

✗ Failed

- Advice** Nearside HEADLAMP BEAM PATTERN POOR
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** EXHAUST PIPE MISSING TAIL END
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #21

2022-10-29 07:21

MOT test number

863502144014

Result

✓ Passed

- Advice** Rear exhaust rear tail pipe corroded slight bit missing

MOT #20

2021-10-25 15:48

MOT test number

462824421799

Result

✓ Passed

- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #19**

2021-10-23 08:18

MOT test number

371640379837

Result

✗ Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #18

2020-10-30 10:25

MOT test number

551333821027

Result

✓ Passed

Advice Nearside Rear Nail in tyre

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Anti-roll bar linkage ball joint has slight play Both sides (5.3.4 (a) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Spy Glass (5.3.4 (a) (i))

**MOT #17**

2020-10-28 15:04

MOT test number

593894061610

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Spy Glass (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn Spy Glass (5.3.4 (a) (i))**Advice** Rear Anti-roll bar linkage ball joint has slight play Both sides (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #16**

2019-04-09 14:57

MOT test number

107527822372

Result

✓ Passed

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2018-04-14 09:04

MOT test number

659331671571

Result

✓ Passed

**MOT #14** 2017-04-27 07:43**MOT test number** 998937937071**Result** ✓ Passed**MOT #13** 2017-04-26 08:42**MOT test number** 185535358980**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #12** 2016-05-20 16:08**MOT test number** 932326796016**Result** ✓ Passed**Advice** Exhaust emissions too low to register**Advice** Offside Rear tyre wearing low inner edge**MOT #11** 2016-05-10 09:58**MOT test number** 776162622078**Result** ✗ Failed**Advice** Exhaust emissions too low to register**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside Rear tyre wearing low inner edge**Fail** Nearside Headlamp aim too low (1.8)**Fail** Nearside Rear Inner Tyre has ply or cords exposed (4.1.D.1b)

**MOT #10**

2015-05-27 12:14

MOT test number

699677445197

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside rear tyre worn on inner edge**MOT #9**

2015-05-27 12:14

MOT test number

246627545177

Result

✗ Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside rear tyre worn on inner edge**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8**

2014-05-31 11:56

MOT test number

228491954433

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7**

2014-05-30 11:07

MOT test number

455770854142

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2013-04-18 16:15**MOT test number** 566168903121**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-04-18 15:02**MOT test number** 446968703133**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-04-03 10:12**MOT test number** 987424092085**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-04-06 14:59**MOT test number** 468886291002**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-04-06 13:11
MOT test number	647706491031
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-04-10 16:33
MOT test number	364800300136
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 October 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2019-06-29
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-04-04
Last registration	2023-10-31
Complete history	See info



Registration #1	2007-04-04	27 mi
Registration #2	2010-04-10	15.598 mi
Registration #3	2011-04-06	26.370 mi
Registration #4	2011-04-06	26.370 mi
Registration #5	2012-04-03	37.200 mi
Registration #6	2013-04-18	46.633 mi
Registration #7	2013-04-18	46.633 mi
Registration #8	2014-05-30	55.893 mi
Registration #9	2014-05-31	55.901 mi
Registration #10	2015-05-27	64.902 mi
Registration #11	2016-05-10	75.092 mi
Registration #12	2016-05-20	76.443 mi
Registration #13	2016-05-20	76.443 mi
Registration #14	2016-05-20	76.443 mi
Registration #15	2016-05-20	76.443 mi
Registration #16	2016-05-20	76.443 mi
Registration #17	2016-05-20	76.443 mi
Registration #18	2016-05-20	76.443 mi
Registration #19	2016-05-20	76.443 mi
Registration #20	2016-05-20	76.443 mi
Registration #21	2016-05-20	76.443 mi
Registration #22	2016-05-20	76.443 mi
Registration #23	2016-05-20	76.443 mi
Registration #24	2016-05-20	76.443 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Engine number	BMM 122233