





General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg





Internet history

Entry 2	
Date	2021-09-16
Pictures	11
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-09-01
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk



2022-01-25

MOT history MOT #18 2021-01-16 10:09 MOT test number 948613624201 Result ✓ Passed

Next expiry date

Advice

Slight engine oil leak

MOT #17	2019-07-19 15:36
MOT test number	216524953375
Result	✓ Passed
Advice Rear both rear coils corroded	
Advice Offside Rear tyre cracking on tread	

MOT #16		2018-07-26 13:13
MOT test	number	203637386479
Result		✓ Passed
Advice (a) (i))	Suspension arm pin or bush worn but not resulting in excessive movem	ent both sides fronts (5.3.4
Advice	Brake disc worn, pitted or scored, but not seriously weakened both side	s fronts (1.1.14 (a) (ii))

MOT #15	2018-07-19 16:11
MOT test number	663279692675
Result	× Failed

Advice Suspension arm pin or bush worn but not resulting in excessive movement both sides fronts (5.3.4 (a) (i))
Advice Brake disc worn, pitted or scored, but not seriously weakened both sides fronts (1.1.14 (a) (ii))
Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))





MOT #14		2017-07-15 10:30
MOT test	number	773133197719
Result		✓ Passed
Advice	Oil leak	
Advice dirt (2.5.C	Offside Front Outer Front constant velocity joint gaiter deteriorated, but .1a)	preventing the ingress of
Advice	Coolant low	
Advice	Coolant leak possible thermostat housing	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #13		2016-07-20 14:45
MOT test	number	760963018022
Result		🗸 Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Oil leak	
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint drop link (2.4.G.2)

MOT #12		2015-07-17 17:30
MOT test	number	788398595172
Result		✓ Passed
Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)		nting the ingress of dirt
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	





MOT #11		2015-07-17 17:30
MOT test number		239148395109
Result		🗙 Failed
Pass with rectifica	Nearside Rear Registration plate lamp not wo	orking (1.1.C.1d)
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)		
Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)		

MOT #10		2014-07-18 16:54
MOT test	number	649969394160
Result		✓ Passed
Notice	Osf cv gaiter prs due to grease visible may need attn	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

МОТ #9	2013-07-12 12:53
MOT test number	189523293118
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Child seat fitted not allowing full inspection of adult belt	

МОТ #8	2012-07-04 11:18
MOT test number	766556382132
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	



MOT #7		2011-07-25 12:41
MOT test n	umber	997836401269
Result		✓ Passed
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Both rear number plate lights slightly dim	
MOT #6		2011-07-24 10:39
MOT test n	umber	416005301240

MOT test number	416005301240
Result	🗙 Failed
Fail Offside Rear coil spring fractured (2.4.C.1a)	
Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice Both rear number plate lights slightly dim	
Advice Offside Side repeater slightly discoloured (1.4.A.2f)	

RA53HZH

report date: 2024-03-28



MOT #5

Result

MOT test number

RA53HZH
report date: 2024-03-28
2010-07-18 15:20
640199490183
✓ Passed

	•
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advic	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advic	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advic	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advic	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #4	2009-07-08 13:06
MOT test number	503399189157
Result	✓ Passed
Notice Oil leak	
MOT #3	2008-07-22 13:22
MOT test number	950374308207
Result	✓ Passed

MOT #2	2007-07-24 12:51
MOT test number	392525607429
Result	✓ Passed





MOT #1	2006-07-25 09:06
MOT test number	212556506268
Result	✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-10-31
Last registration	2021-01-16
Complete history	<u>See info</u>



Registration #1	2003-10-31	13 mi
Registration #2	2006-07-25	24.240 mi
Registration #3	2007-07-24	32.930 mi
Registration #4	2008-07-22	38.361 mi
Registration #5	2009-07-08	44.862 mi
Registration #6	2010-07-18	51.893 mi
Registration #7	2011-07-24	59.387 mi
Registration #8	2011-07-25	59.407 mi
Registration #9	2012-07-04	65.749 mi
Registration #10	2013-07-12	73.802 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		01.777 est
Deviaturation #10		
Registration #19		11,717 46
Registration #19 Registration #20		11,000 au







Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1262 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number CarCheck.co.uk	FX3V2063253 page 14/14