





report date: 2024-03-28

#### General information

Make	ТОУОТА
Model	CELICA VVTI
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/12




report date: 2024-03-28

### Internet history


#### Entry 1

Date	2021-08-02	
Pictures	16	
Listing price	View report	









source: autotrader.co.uk

CarCheck.co.uk page 2/12



**MOT** history

**MOT #24** 2022-11-16 11:17

MOT test number 825135541602

**Result** ✓ Passed

Next expiry date 2023-11-17

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #23 2022-11-16 11:17

MOT test number 142034270906

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Pass with rectification Front Position lamp not working both (4.2.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #22** 2021-11-18 10:52

**MOT test number** 648114477572

**Result** ✓ Passed

**MOT #21** 2020-10-31 17:31

MOT test number 955638473639

Result \( \sqrt{Passed} \)

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #20

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

143266057394

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #18
 2018-05-02 13:35

 MOT test number
 575305896615

 Result
 ✓ Passed

 MOT #17
 2018-05-02 09:20

 MOT test number
 101799305993

 Result
 X Failed

 Fail
 Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #16
 2017-05-06 11:49

 MOT test number
 480666700551

 Result
 ✓ Passed

 MOT #15
 2016-05-07 09:32

 MOT test number
 978624475662

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #14

MOT test number

Failed

Result

Rear Stop lamp not working (1.2.1b)

MOT #13

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #12
 2014-05-03 13:54

 MOT test number
 837523624189

 Result
 ✓ Passed

MOT #11

MOT test number

Result

Pass with rectification

Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #10

MOT test number

799503803125

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #9
 2012-05-05 11:39

 MOT test number
 658886322123

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

 MOT #8
 2011-05-11 14:29

 MOT test number
 575101531130

**MOT #7** 2010-05-06 16:09

MOT test number 250046920103

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2009-05-05 17:23

**MOT test number** 650965029176

Result \rightarrow Passed

**MOT #5** 2009-05-05 17:23

MOT test number 120045629188

Result X Failed

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

MOT #4 2008-04-21 16:54

**MOT test number** 931452418191

**Result** ✓ Passed

MOT #3 2008-04-21 16:03

**MOT test number** 780912618143

**Result** X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/12



MOT #2	2007-04-24 14:44
MOT test number	273404917139
Result	✓ Passed
MOT #1	2006-04-06 15:49
MOT test number	132966496462
Result	✓ Passed

CarCheck.co.uk page 7/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NK NK
Flate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-04-01
Last registration	2022-11-16
Complete history	See info



Registration #1	2001-04-01	13 mi
Registration #2	2006-04-06	42.602 mi
Registration #3	2007-04-24	48.052 mi
Registration #4	2008-04-21	53.683 mi
Registration #5	2008-04-21	53.684 mi
Registration #6	2009-05-05	58.708 mi
Registration #7	2010-05-06	64.064 mi
Registration #8	2011-05-11	69.864 mi
Registration #9	2012-05-05	71.107 mi
Registration #10	2013-04-13	71.990 mi
Registration #11	2014-05-03	72.780 mi
Registration #12	2015-05-09	73.286 mi
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		71,777 66
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		71.777 es

More info >



#### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ0771609

CarCheck.co.uk page 12/12