





report date: 2024-03-29

General information

Make	NISSAN
Model	NAVARA DCI ACENTA 4X4 DCB
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	33.2 mpg



CarCheck.co.uk page 1/12




Internet history


Entry 2

Date	2022-02-09

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-11
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-15
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #11	2024-02-14 14:59
MOT test number	884043069039
Result	✓ Passed
Next expiry date	2025-02-15

MOT #10		2023-02-16 16:02
MOT test	number	799036340683
Result		✓ Passed
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #9		2022-02-16 13:21
MOT test	number	802631743024
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2021-01-20 17:14
MOT test number	885629797698
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT test number

737815316825

Result

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

MOT #6 2018-06-12 14:02 **MOT** test number 164245908270 Result × Failed **Fail** Nearside Rear Leaf spring fractured (5.3.1 (b) (i)) **Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c)) **Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c)) Advice Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #5	2017-06-06 16:07
MOT test number	493304185207
Result	✓ Passed
Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2) Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	

CarCheck.co.uk page 4/12



MOT test number

Result

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice

Front Propshaft universal joint worn rear u/j worn

Advice

Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Fail

Offside Side repeater not working (1.4.A.2c)

MOT test number

Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

817775655126

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT test number

Result

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside front wiper blade split but still clearing windscreen efficiently

Notice Spare tyre defective

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status

Days left

MOT expiry date

Full MOT history

See MOT history

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	hictor,
UWNEI	nisioiv

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
have: Check it in the premium report and see an owner registrations. Download the full r	eport <u>nere</u> .

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK UK
Rinto circo	UK C
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-02-04
Last registration	2024-02-14
Complete history	See info



Registration #1	2011-02-04	8 mi
Registration #2	2014-02-01	22.817 mi
Registration #3	2015-06-04	36.232 mi
Registration #4	2016-06-01	45.963 mi
Registration #5	2017-06-02	56.554 mi
Registration #6	2017-06-06	56.555 mi
Registration #7	2018-06-12	68.475 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	★★★ ★★
Video	see crash video



Dimensions & weight

Width	1848 mm
Height	1905 mm
Length	5296 mm
Kerb weight	2085 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	81893B

CarCheck.co.uk page 12/12