



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV4 VVT-I XT3
Colour	Grey
Year of manufacture	2003
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	207 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-06-06
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-30
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	35
Total items failed	1

MOT #21	2023-07-31 11:26
---------	------------------

MOT test number	866522029840
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-30
------------------	------------

- Advice
- Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice
- Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice
- Coil spring corroded both fronts (5.3.1 (b) (i))
- Advice
- Tyre slightly damaged/cracking or perishing both fronts (5.2.3 (d) (ii))
- Advice
- Offside Rear Tyre has a cut but not deep enough to reach the ply or cords also perished (5.2.3 (d) (i))
- Advice
- Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2023-07-25 12:01

**MOT test number**

527023561636

**Result****✗ Failed****Advice**

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice**

Tyre slightly damaged/cracking or perishing both fronts (5.2.3 (d) (ii))

**Advice**

Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice**

Coil spring corroded both fronts (5.3.1 (b) (i))

**MAJOR**

Brake performance unable to be tested due to dangerous failure (1.2.1 (g))

**DANGEROUS**

Driver's seat insecure (6.2.5 (a) (ii))

**MAJOR**

Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords also perished (5.2.3 (d) (i))

**MOT #19**

2022-07-22 11:35

**MOT test number**

630624425459

**Result****✓ Passed****Minor**

Offside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #18**

2022-07-19 09:07

**MOT test number**

316870263996

**Result****✗ Failed****MAJOR**

Nearside Rear Brake pipe excessively corroded ton flex hose (1.1.11 (c))

**MAJOR**

Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MAJOR**

Offside Rear Brake pipe excessively corroded to flex hose (1.1.11 (c))

**MOT #17**

2021-07-21 13:16

**MOT test number**

556037440048

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2021-07-19 12:42

**MOT test number**

369684241371

**Result**

✗ Failed

- DANGEROUS** Nearside Rear Passenger's seat insecure (6.2.6 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Offside Front Driver's seat insecure (6.2.5 (a) (ii))
- MAJOR** Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s (5.3.4 (a) (i))

**MOT #15**

2020-07-30 15:09

**MOT test number**

222913502581

**Result**

✓ Passed

**MOT #14**

2019-04-29 15:25

**MOT test number**

794500050156

**Result**

✓ Passed

**MOT #13** 2018-05-01 12:37**MOT test number** 439458491007**Result** ✓ Passed**Advice** Brake pipe slightly corroded both rear (3.6.B.2c)**MOT #12** 2017-05-02 09:59**MOT test number** 248290409611**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded Both side. (3.6.B.2c)**MOT #11** 2016-05-07 10:31**MOT test number** 574331364901**Result** ✓ Passed**Advice** Front Both tyre deteriorated .**Advice** Rear Both tyre deteriorated .**MOT #10** 2015-05-06 15:40**MOT test number** 297116225135**Result** ✓ Passed**MOT #9** 2014-03-17 11:09**MOT test number** 446966774023**Result** ✓ Passed**MOT #8** 2013-03-19 09:42**MOT test number** 837108773084**Result** ✓ Passed



<b>MOT #7</b>	2013-03-18 14:22
<b>MOT test number</b>	126047473042
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
<b>MOT #6</b>	2012-06-15 14:47
<b>MOT test number</b>	956477462134
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2011-06-13 14:13
<b>MOT test number</b>	437564461163
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2010-06-17 14:56
<b>MOT test number</b>	204328960431
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2009-06-15 15:09
<b>MOT test number</b>	204766969467
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2008-06-23 16:45
<b>MOT test number</b>	922915278173
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2007-06-28 12:07
<b>MOT test number</b>	240949177144
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
30 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	30 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-11-08
Last registration	2023-07-31
Complete history	<a href="#">See info</a>



Registration #1	2003-11-08	8 mi
Registration #2	2007-06-28	23.179 mi
Registration #3	2008-06-23	32.126 mi
Registration #4	2009-06-15	38.645 mi
Registration #5	2010-06-17	44.533 mi
Registration #6	2011-06-13	48.933 mi
Registration #7	2012-06-15	54.570 mi
Registration #8	2013-03-18	58.217 mi
Registration #9	2013-03-19	58.217 mi
Registration #10	2014-03-17	62.908 mi
Registration #11	2015-05-06	67.911 mi
Registration #12	2016-05-07	71.512 mi
Registration #13	2017-05-07	75.112 mi
Registration #14	2018-05-07	78.712 mi
Registration #15	2019-05-07	82.312 mi
Registration #16	2020-05-07	85.912 mi
Registration #17	2021-05-07	89.512 mi
Registration #18	2022-05-07	93.112 mi
Registration #19	2023-05-07	96.712 mi
Registration #20	2024-05-07	100.312 mi
Registration #21	2025-05-07	103.912 mi
Registration #22	2026-05-07	107.512 mi
Registration #23	2027-05-07	111.112 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1695 mm
Length	3805 mm
Wheel base	2280 mm
Kerb weight	1325 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1AZ1260810