



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2025-02-09
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	55
Total items failed	23

MOT #202024-02-07 14:12

MOT test number805067249791

Result✓ Passed

Next expiry date2025-02-09

- Advice** Front Lower Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Both sills (5.3.6 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill end (5.3.6 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2024-01-29 11:23

MOT test number

690951773979

Result**✗ Failed****Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill end (5.3.6 (a) (i))**Advice** Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Both sills (5.3.6 (a) (i))**Fail** Offside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))**Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Lower Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill end (5.3.6 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))**MOT #18**

2023-02-04 14:06

MOT test number

256042608003

Result**✓ Passed****Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2023-02-03 14:06

MOT test number

642148047967

Result**✗ Failed**

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2022-02-10 10:32

MOT test number

651909923640

Result**✓ Passed**

Advice Both rear spring cups corroded

MOT #15

2022-02-08 10:22

MOT test number

997727323799

Result**✗ Failed**

Fail Offside Rear Position lamp has a product on the lens or light source which shows white light to the rear (4.2.3 (b) (ii))

Advice Both rear spring cups corroded

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

Fail Offside Front Driver's seat insecure (6.2.5 (a) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #14** 2021-02-10 15:28**MOT test number** 487396617889**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #13** 2021-02-10 13:20**MOT test number** 847978653661**Result** ✗ Failed**Fail** Rear Stop lamp(s) not working both side (4.3.1 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #12** 2019-05-08 13:06**MOT test number** 740275275021**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Exhaust mounting corroded mid pipe**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Covers fitted at time of test**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front tyres damaged on side wall

**MOT #11**

2019-05-03 11:09

MOT test number

114139546161

Result**✗ Failed**

- Advice** Offside Rear Brake flexible hose securing bracket missing
- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Exhaust has a major leak of exhaust gases hole in DPF (6.1.2 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** DPF has had a previous welded repair which is now leaking
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear exhaust heat shield insecure
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #10

2018-05-02 09:53

MOT test number

197901682874

Result**✓ Passed****MOT #9**

2017-04-10 08:49

MOT test number

310633687283

Result**✓ Passed**

**MOT #8** 2016-05-06 13:23**MOT test number** 142273413887**Result** ✓ Passed**MOT #7** 2016-05-04 09:38**MOT test number** 469414803841**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Fail** Front Exhaust has a major leak of exhaust gases dpf (7.1.2)

MOT #6 2015-04-16 15:27**MOT test number** 176236505155**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2015-04-15 10:55**MOT test number** 455965505127**Result** ✗ Failed

- Fail** Offside Inner Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Inner Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4** 2014-05-08 12:36**MOT test number** 335908024116**Result** ✓ Passed**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2013-09-17 11:10**MOT test number** 606170363244**Result** ✓ Passed**Advice** Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #2** 2013-05-02 15:14**MOT test number** 665042923182**Result** ✓ Passed**MOT #1** 2012-11-12 09:42**MOT test number** 538947712325**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-11-25
Last registration	2024-02-07
Complete history	See info



Registration #1	2009-11-25	20 mi
Registration #2	2012-11-12	69.073 mi
Registration #3	2013-05-02	74.653 mi
Registration #4	2013-09-17	74.662 mi
Registration #5	2014-05-08	81.849 mi
Registration #6	2015-04-15	93.894 mi
Registration #7	2015-04-16	93.897 mi
Registration #8	2016-05-04	105.354 mi
Registration #9	2016-05-06	105.368 mi
Registration #10	2017-04-10	111.177 mi
Registration #11	2018-05-02	120.811 mi
Registration #12	2019-05-02	130.811 mi
Registration #13	2020-05-02	140.811 mi
Registration #14	2021-05-02	150.811 mi
Registration #15	2022-05-02	160.811 mi
Registration #16	2023-05-02	170.811 mi
Registration #17	2024-02-07	180.811 mi
Registration #18	2024-02-07	190.811 mi
Registration #19	2024-02-07	200.811 mi
Registration #20	2024-02-07	210.811 mi
Registration #21	2024-02-07	220.811 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C62374