



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Brown
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #14	2022-10-11 09:37
MOT test number	738055354644
Result	✓ Passed
Next expiry date	2023-10-16
Advice Nearside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))	
Advice Offside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))	

MOT #13	2021-10-07 10:19
MOT test number	730442597692
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	

MOT #12	2020-10-17 08:19
MOT test number	264629469468
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))	

MOT #11	2019-06-15 09:04
MOT test number	240443667424
Result	✓ Passed

MOT #10	2018-06-18 14:56
MOT test number	423567274327
Result	✓ Passed

**MOT #9** 2018-01-20 12:22**MOT test number** 711263842073**Result** ✓ Passed**Advice** Offside Front tyre has side wall damage.**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Nearside Front tyre worn on outer edge.**MOT #8** 2017-01-27 10:11**MOT test number** 141356022790**Result** ✓ Passed**MOT #7** 2017-01-27 10:11**MOT test number** 256052061791**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2016-01-26 12:55**MOT test number** 452482953787**Result** ✓ Passed**MOT #5** 2015-12-08 14:40**MOT test number** 646582627110**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage steering rack pipes (2.3.3b)**Advice** Rear exhaust bracket corroding and slightly loose

**MOT #4** 2015-12-08 12:36**MOT test number** 299081506136**Result** ✗ Failed**Advice** Power steering pipe(s) or hose(s) has slight seepage steering rack pipes (2.3.3b)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear exhaust bracket corroding and slightly loose**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2014-12-08 10:46**MOT test number** 578332244378**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**MOT #2** 2013-12-18 10:34**MOT test number** 446532453435**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #1** 2012-12-17 10:52**MOT test number** 477252652459**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-01-21
Last registration	2022-10-11
Complete history	See info



Registration #1	2010-01-21	15 mi
Registration #2	2012-12-17	19.976 mi
Registration #3	2013-12-18	26.513 mi
Registration #4	2014-12-08	33.457 mi
Registration #5	2015-12-08	40.540 mi
Registration #6	2015-12-08	40.541 mi
Registration #7	2016-01-26	40.836 mi
Registration #8	2017-01-27	55.610 mi
Registration #9	2019-05-29	55.577 mi
Registration #10	2019-05-29	55.577 mi
Registration #11	2019-05-29	55.577 mi
Registration #12	2019-05-29	55.577 mi
Registration #13	2019-05-29	55.577 mi
Registration #14	2019-05-29	55.577 mi
Registration #15	2019-05-29	55.577 mi
Registration #16	2019-05-29	55.577 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3431903