





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	JETTA SE FSI
Colour	Blue
Year of manufacture	2007
Top speed	131 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg
CO2 emission	192 g/km
CO2 label	J



CarCheck.co.uk page 1/13



DU07GYF report date: 2024-03-29

Internet history

	-	4.	M3 /	- 1
ᆮ	п	ш	ľV	- 1

ciitiy 1	
Date	2021-09-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2023-09-06
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #16	2022-08-16 13:56
MOT test number	600709485522
Result	✓ Passed
Next expiry date	2023-09-06

MOT #15		2021-08-24 10:55
MOT test i	number	762618736495
Result		✓ Passed
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously reduc	ing light output (4.1.4
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducin	g light output (4.1.4

MOT #14	2020-08-28 14:16
MOT test number	378254446980
Result	✓ Passed
Advice Both Front Head Lights Deteriorated	

MOT #13	2019-08-28 13:30
MOT test number	761565434166
Result	✓ Passed
Advice Both rear tyres wearing on inner edges	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2018-09-01 11:25 938073607489 **MOT** test number Result ✓ Passed **Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i)) **Advice** Offside Front wheel slight binding on wheel rotation Advice Offside Rear Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e)) Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #11 2017-09-07 10:35

MOT test number 392929741282

Result ✓ Passed

MOT test number 457514507655

Result ✓ Passed

Advice Both front wiper rubbers starting to split

Advice Nearside rear tyre tread worn inside edge

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' small chips (8.3.1a)

Advice Both front headlamps lenses scratched

MOT #9

MOT test number

464859146465

Result

Advice Rear stone cuts to tyre treads

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8	2015-04-01 12:59
MOT test number	175921795004
Result	✓ Passed
Notice Advise windscreen cracked	

MOT #7	2014-04-10 14:12
MOT test number	399370204191
Result	✓ Passed
MOT #6	2013-04-04 15:18
MOT test number	109684193469
Result	✓ Passed
Notice Nearside front tyre on 3mm	
Notice Offside front tyre on 3mm	


MOT #5	2013-04-03 14:51
MOT test number	398493893039
Result	X Failed
Notice Nearside front tyre on 3mm	
Fail Fuel system component leaking (7.2.3)	
Notice Offside front tyre on 3mm	

MOT #4	2012-04-07 09:53
MOT test number	915438292038
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29



MOT #2		2011-02-17 13:01
MOT test	number	937518441019
Result		✓ Passed
Notice	ESP light on dash	
Notice	Rear offside and nearside trye's cracking on tread	
Notice	Front offside and nearside brake disc's corroded on face's	

MOT #1	2010-02-16 12:01
MOT test number	953607740027
Result	✓ Passed
Notice Both front tyres on 3mm	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax expired: 1 February 2024

X MOT

Expired: 6 September 2023

Tax status	Expired at 1 February 2024
Days left	88 days too late
MOT expiry date	6 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many of VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Mumber of plates	,
Current registration	UK NEZ
Plate since	
Current registration	NK NK
Plate since	

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-01
Last registration	2022-08-16
Complete history	See info



Registration #1	2007-03-01	29 mi
Registration #2	2010-02-16	18.030 mi
Registration #3	2011-02-17	25.445 mi
Registration #4	2012-04-05	30.882 mi
Registration #5	2012-04-07	30.882 mi
Registration #6	2013-04-03	35.680 mi
Registration #7	2013-04-04	35.680 mi
Registration #8	2014-04-10	44.102 mi
Registration #9	2015-04-01	53.208 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 12/13



DU07GYF report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

here.

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1473 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack co.uk	nago 12/1:

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	BVY 078488