



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D5 SE
Colour	Blue
Year of manufacture	2010
Top speed	146 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2021-12-08
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #10	2020-12-09 17:43
MOT test number	298776523582
Result	✓ Passed
Next expiry date	2021-12-08
Advice	Offside Front Nail in tyre

MOT #9	2019-12-09 17:44
MOT test number	866184777459
Result	✓ Passed

MOT #8	2019-12-09 17:44
MOT test number	120253390489
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))

MOT #7	2018-12-08 08:47
MOT test number	818969748398
Result	✓ Passed



MOT #6	2017-12-09 09:25
---------------	------------------

MOT test number	265682547605
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-12-17 09:18
---------------	------------------

MOT test number	605642319453
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-12-31 10:23
---------------	------------------

MOT test number	567939928675
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-01-10 11:37
---------------	------------------

MOT test number	915290615031
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-11-21 16:04
---------------	------------------

MOT test number	486645723445
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Under-trays fitted obscuring some underside components
---------------	--

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

Notice	Engine covers fitted obscuring some components in the engine bay
---------------	--



MOT #12013-11-21 11:46

MOT test number807215023334

Result

Failed

- Fail

Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice

Under-trays fitted obscuring some underside components
- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✕
Untaxed

Tax expired:
5 March 2021

✕
MOT

Expired:
8 December 2021

Tax status	Expired at 5 March 2021
Days left	1150 days too late
MOT expiry date	8 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-12-20
Last registration	2020-12-09
Complete history	See info



Registration #1	2010-12-20	9 mi
Registration #2	2013-11-21	38.736 mi
Registration #3	2013-11-21	38.736 mi
Registration #4	2015-01-10	55.166 mi
Registration #5	2015-12-31	66.468 mi
Registration #6	2016-12-17	80.614 mi
Registration #7	2019-05-20	95.277 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2775 mm
Kerb weight	1601 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	855333