





report date: 2024-03-28

General information

Make	VAUXHALL
Model	CASCADA SE CDTI S/S
Colour	Grey
Year of manufacture	2014
Top speed	135 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	165 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.956 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-02

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-08-29

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #9	2023-06-15 10:16
MOT test number	107389809706
Result	✓ Passed
Next expiry date	2024-06-20

MOT #8	2022-06-21 14:03
MOT test number	823739671877
Result	✓ Passed

MOT #7	2021-08-02 14:15
MOT test number	654706666954
Result	✓ Passed

MOT #	6	2021-07-30 10:11
MOT te	st number	562314296868
Result		★ Failed
Fail	Nearside Headlamp aim too high (4.1.2 (a))	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4

MOT test number

637066848536

Result

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

O/s/f and n/s/f tyre treads 3mm and wearing on inner edges

MOT #2

MOT test number

713958843239

Result

✓ Passed

MOT #1

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

2017-01-24 09:28

330986344499

✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIN
Flate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-01-24
Last registration	2023-06-15
Complete history	See info



Registration #1	2014-01-24	27 mi
Registration #2	2017-01-24	31.416 mi
Registration #3	2018-01-16	39.889 mi
Registration #4	2019-07-31	54.697 mi
Registration #5	2020-07-22	64.062 mi
Registration #6	2020-07-23	64.099 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11





report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1741 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	A20DTH -17A95920LBS

CarCheck.co.uk page 11/11