



LSIOVWA

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC 110
Colour	Blue
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-21
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-10-19
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	21
Total items failed	13

MOT #13	2020-10-20 14:28
MOT test number	146530538021
Result	✓ Passed
Next expiry date	2021-10-19
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12	2020-10-20 10:32
MOT test number	392589219079
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Fail	Nearside Front Headlamp aim not tested (4.1.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Front Side repeater not working (4.4.1 (a) (ii))

MOT #11	2019-09-19 14:12
MOT test number	169247607356
Result	✓ Passed



MOT #10	2019-09-17 16:33
MOT test number	526865465917
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #9	2018-09-03 13:22
MOT test number	472516371905
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Outer sills dented both sides

MOT #8	2018-08-28 11:49
MOT test number	973909223556
Result	✗ Failed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Advice	Outer sills dented both sides
Fail	Offside Front Position lamp not working (4.2.1 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7** 2017-09-05 14:48**MOT test number** 923431726199**Result** ✓ Passed**Advice** Bonnet hard to open**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2017-09-05 10:51**MOT test number** 735972265893**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Advice** Bonnet hard to open**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Rear parking brake recording little or no effort Both rear (3.7.B.6a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Headlamp aim too low (1.8)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #5** 2016-09-12 12:04**MOT test number** 325079315322**Result** ✓ Passed**MOT #4** 2015-09-14 15:19**MOT test number** 976172890230**Result** ✓ Passed



MOT #3	2014-09-22 14:49
MOT test number	297695664255
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2013-09-25 09:55
MOT test number	279008663267
Result	✓ Passed

MOT #1	2013-05-10 10:39
MOT test number	986920033169
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Evidence of RATS Under Bonnet...
Notice	Engine covers fitted obscuring some components in the engine bay



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-16
Last registration	2020-10-20
Complete history	See info



Registration #1	2010-06-16	18 mi
Registration #2	2013-05-10	12.873 mi
Registration #3	2013-09-25	13.527 mi
Registration #4	2014-09-22	29.572 mi
Registration #5	2015-09-14	45.180 mi
Registration #6	2016-09-12	59.204 mi
Registration #7	2017-09-05	73.752 mi
Registration #8	2017-09-05	73.752 mi
Registration #9	2018-09-05	73.752 mi
Registration #10	2018-09-05	73.752 mi
Registration #11	2018-09-05	73.752 mi
Registration #12	2018-09-05	73.752 mi
Registration #13	2018-09-05	73.752 mi
Registration #14	2018-09-05	73.752 mi
Registration #15	2018-09-05	73.752 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU23426