



report date: 2024-03-29

General information

Make	MAZDA
Model	2 TAMURA
Colour	Grey
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-31
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #11	2024-01-30 16:51
MOT test number	584436476474
Result	✓ Passed
Next expiry date	2025-01-31
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #10	2023-01-25 15:17
MOT test number	984382211110
Result	✓ Passed

MOT #9	2023-01-25 09:52
MOT test number	638056130217
Result	✗ Failed
Fail	Offside Front Tyre has a lump, caused by separation or partial failure of its structure inner side wall (5.2.3 (d) (ii))
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords inner side wall (5.2.3 (d) (i))

MOT #8	2022-02-01 11:10
MOT test number	632271162482
Result	✓ Passed

**MOT #7** 2020-08-28 15:50**MOT test number** 989400199043**Result** ✓ Passed**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear heat shield by tank not fully secured**MOT #6** 2020-08-25 15:59**MOT test number** 716911861185**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear heat shield by tank not fully secured**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #5** 2019-09-04 08:58**MOT test number** 240301620725**Result** ✓ Passed**MOT #4** 2018-08-28 15:09**MOT test number** 838962308614**Result** ✓ Passed**Advice** Both rear tyres worn unevenly and bald on inner edges**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #3	2017-08-18 14:28
MOT test number	618587052424
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Both rear tyres worn uneven and perished
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2016-08-09 13:52
MOT test number	472588846297
Result	✓ Passed

MOT #1	2015-08-07 08:26
MOT test number	315761431724
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	VO62CTV
Plate since	2019-09-29
Current registration	VO62CTV
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-05
Last registration	2024-01-30
Complete history	See info



Registration #1	2012-09-05	12 mi
Registration #2	2015-08-07	23.061 mi
Registration #3	2016-08-09	34.240 mi
Registration #4	2017-08-18	47.709 mi
Registration #5	2018-08-28	58.345 mi
Registration #6	2019-09-04	66.427 mi
Registration #7	2020-08-25	71.037 mi
Registration #8	2021-08-25	75.277 mi
Registration #9	2022-08-25	79.517 mi
Registration #10	2023-08-25	83.757 mi
Registration #11	2024-01-30	87.997 mi
Registration #12		
Registration #13		

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ A50824