



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-5 D SPORT NAV
Colour	White
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-07
Pictures	61
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	4

MOT #6	2024-01-26 14:39
MOT test number	442701601779
Result	✓ Passed
Next expiry date	2025-01-25
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5	2023-01-25 15:08
MOT test number	368830239862
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4	2023-01-25 11:26
MOT test number	121897058373
Result	✗ Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #3	2022-01-10 15:31
MOT test number	803174360554
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #2** 2021-01-02 13:37**MOT test number** 198555919365**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2021-01-02 13:37**MOT test number** 449101069639**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Pass with rectification** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-12
Last registration	2024-01-26
Complete history	See info



Registration #1	2018-01-12	27 mi
Registration #2	2021-01-02	49.152 mi
Registration #3	2021-01-02	49.152 mi
Registration #4	2022-01-02	50.277 mi
Registration #5	2023-01-02	51.402 mi
Registration #6	2024-01-26	52.527 mi
Registration #7		
Registration #8		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Wheel base	2700 mm
Kerb weight	1594 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30832351