



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg








Internet history

Entry 1

Date	2021-06-28
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #20 2022-04-26 15:26

MOT test number 820784204043

Result ✓ Passed

Next expiry date 2023-04-27

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Front Coil spring sat incorrectly
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2022-04-19 15:14

MOT test number

604414839805

Result**✗ Failed**

- MAJOR** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material Rear of front to rear (1.1.11 (c))
- MAJOR** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Advice** Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Inner Brake pipe excessively corroded (1.1.11 (c))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Rear of front to rear (1.1.11 (c))
- MAJOR** Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- MAJOR** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced Outer sill (7.1.1 (a) (i))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Front Coil spring sat incorrectly
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear Outer Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Rear Inner Brake pipe excessively corroded (1.1.11 (c))

**MOT #18** 2021-04-21 06:18**MOT test number** 292335830515**Result** ✓ Passed**Advice** Both outer sill weak**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #17** 2020-04-08 05:58**MOT test number** 763017291200**Result** ✓ Passed**Advice** Nearside Front outer sill weak**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2019-04-17 06:46**MOT test number** 618789402724**Result** ✓ Passed**Advice** Nearside Front outer sill slightly weak**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #15** 2018-04-19 06:14**MOT test number** 518433325840**Result** ✓ Passed**MOT #14** 2018-04-19 06:14**MOT test number** 608213149248**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #13**

2018-04-13 08:35

MOT test number

455295522289

Result**✗ Failed****Advice** Nearside Front Brake pipe slightly corroded wheel arch (3.6.B.2c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Direction indicators adversely affected by the operation of another lamp causes other lights to flash on fog lamp, reverse and brake lamp (1.4.A.2h)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #12**

2017-04-18 12:19

MOT test number

868729849816

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pipe slightly corroded front to rear (3.6.B.2c)**MOT #11**

2016-04-26 11:10

MOT test number

591429762106

Result**✓ Passed****Advice** Nearside Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #10** 2016-04-20 08:27**MOT test number** 321571090608**Result** ✗ Failed**Fail** Offside Headlamp not working on main beam (1.7.5a)**Fail** Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)**Advice** Nearside Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Offside Front constant velocity joint is insecure (2.5.C.1b)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**MOT #9** 2015-04-22 10:23**MOT test number** 237072015409**Result** ✓ Passed**MOT #8** 2014-04-22 15:24**MOT test number** 226932014450**Result** ✓ Passed**MOT #7** 2014-04-22 10:12**MOT test number** 538682814184**Result** ✗ Failed**Fail** Rear Tyre has had the tread recut (4.1.D.1c)**Fail** Offside Front Tyre has had the tread recut (4.1.D.1c)**MOT #6** 2013-04-22 16:10**MOT test number** 107202113168**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-04-22 11:07**MOT test number** 395142113117**Result** ✗ Failed**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Notice** O/s/r tyre outer wall cracked**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Both rear tyres outer wall cracked**MOT #4** 2012-04-23 10:13**MOT test number** 658964712172**Result** ✓ Passed**Notice** O/s/f and n/s/r tyre treads cracking**MOT #3** 2011-04-19 11:12**MOT test number** 227309301465**Result** ✓ Passed**MOT #2** 2010-04-23 10:26**MOT test number** 221683410153**Result** ✓ Passed**MOT #1** 2009-04-09 12:35**MOT test number** 544089799054**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-04-27
Last registration	2022-04-26
Complete history	See info



Registration #1	2006-04-27	9 mi
Registration #2	2009-04-09	15.811 mi
Registration #3	2010-04-23	17.027 mi
Registration #4	2011-04-19	18.474 mi
Registration #5	2012-04-23	19.671 mi
Registration #6	2013-04-22	20.504 mi
Registration #7	2013-04-22	20.504 mi
Registration #8	2014-04-22	21.235 mi
Registration #9	2014-04-22	21.235 mi
Registration #10	2015-04-22	26.364 mi
Registration #11	2016-04-20	34.273 mi
Registration #12	2016-04-20	34.273 mi
Registration #13	2016-04-20	34.273 mi
Registration #14	2016-04-20	34.273 mi
Registration #15	2016-04-20	34.273 mi
Registration #16	2016-04-20	34.273 mi
Registration #17	2016-04-20	34.273 mi
Registration #18	2016-04-20	34.273 mi
Registration #19	2016-04-20	34.273 mi
Registration #20	2016-04-20	34.273 mi
Registration #21	2016-04-20	34.273 mi
Registration #22	2016-04-20	34.273 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3097262