





report date: 2024-03-28

### General information

Make	MAZDA
Model	6 SPORT NAV
Colour	Red
Year of manufacture	2015
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	163 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-09-14

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



SV65NWS report date: 2024-03-28

MOT history

MOT expiry date	2024-09-14
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #7	2023-09-15 15:07
MOT test number	897339754373
Result	<b>✓</b> Passed
Next expiry date	2024-09-14
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #6		2023-09-14 11:37
MOT test	number	669779751599
Result		<b>X</b> Failed
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #5		2022-09-01 15:53
MOT test	number	126020593787
Result		<b>✓</b> Passed
Advice (c))	Nearside Rear Brake pipe corroded, covered in grease or other	material brake pipe rusty (1.1.11

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4		2021-08-11 14:32
MOT test	number	870786346096
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2020-09-09 15:4	4
MOT test	number 23211118716	3
Result	✓ Passe	d
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Under trays fitted	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #2	2019-08-21 18:12
MOT test number	104445099925
Result	<b>✓</b> Passed
MOT #1	2018-09-03 10:21
MOT test number	768946106728
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

<b>O</b>	ner	1-:-	A
( )\/	mar.	nıc	TCCC
		шэ	

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
**************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK NEW
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-08
Last registration	2023-09-15
Complete history	See info



Registration #1	2015-09-08	22 mi
Registration #1	2013-09-00	22 1111
Registration #2	2018-09-03	20.272 mi
Registration #3	2019-08-21	22.573 mi
Registration #4	2020-09-09	28.304 mi
Registration #5	2021-08-11	35.592 mi
Registration #6		11.777 es
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2830 mm
Kerb weight	1310 kg
Max. allowed weight	1945 kg

### Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	PE 20663488

CarCheck.co.uk page 11/11