





General information

Make	NISSAN
Model	NOTE ACENTA
Colour	Blue
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В







Internet history

Entry 2	
Date	2021-06-14
Pictures	8
Listing price	View report



source: yesauto.com

Entry	1
-------	---

Date

Pictures

Listing price

2021-05-25 40

View report



source: autotrader.co.uk









MOT history

MOT expiry date	2025-03-01
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	14
Total items failed	0

МОТ #6	2024-02-16 10:48
MOT test number	605648344589
Result	🗸 Passed
Next expiry date	2025-03-01
Advice Nearside Front Brake disc worn, pitted or scored, but not serious	ily weakened (1.1.14 (a) (ii))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))	

MOT #5	2023-02-13 13:16
MOT test number	226602338141
Result	✓ Passed
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.3	1.11 (c))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excess bush (5.3.4 (a) (i))	ssive movement front





MOT #4	2022-03-01 09:56	
MOT test number	602228642581	
Result	✓ Passed	
AdviceOffside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))AdviceOffside Front Lower Suspension arm pin or bush worn but not resulting in excessive movementfront bush (5.3.4 (a) (i))		
MOT #3	2021-02-22 10:39	

MOT test	number	864849622096
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 1955516 (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive possible sump seal (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 1955516 (5.2.3 (d) (ii))	

MOT #2		2020-03-02 14:53
MOT test nu	mber	738785280682
Result		✓ Passed
Advice C	Dil leak, but not excessive (8.4.1 (a) (i))	
Advice T	yre slightly damaged/cracking or perishing Both rears (5.2.3 (d) (ii))	
MOT #1		2019-02-19 12:06

MOT #1	2019-02-19 12:06
MOT test number	683288202173
Result	✓ Passed



Tax & MOT check

Tax due: 1 June 2024	√ axed	Expires: 1 March 2025	✓ мот
Tax status			Valid until 1 June
Days left			33
MOT expiry date			1 March 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second s	

	More info >
Plate changes See in this check if this NISSAN had different number plate	S.
Number of plates	
Carrent registration	
Plate since	
Current registration	
Rate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-01
Last registration	2024-02-16
Complete history	See info



Registration #1	2016-03-01	8 mi
Registration #2	2019-02-19	17.160 mi
Registration #3	2020-03-02	27.316 mi
Registration #4	2021-02-22	30.565 mi
Registration #5		11.777 esi
Registration #6		11.117 esi
Registration #7		11.777 esi
Registration #8		11.117 esi
Registration #9		11.777 esi

More info >






Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1040 kg
Max. allowed weight	1510 kg
Additional information	
Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	105059R