



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	White
Year of manufacture	2006
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-10-01
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	63
Total items failed	3

MOT #20 2024-01-04 08:39

MOT test number 559177698623

Result ✓ Passed

Next expiry date 2025-01-11

- Advice** Nearside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19 2023-01-12 15:52

MOT test number 175518279447

Result ✓ Passed

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** O/s no.plate lens insecure
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**MOT #18**

2022-12-19 11:14

MOT test number

318414135824

Result**✗ Failed****MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))**MAJOR** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))**MOT #17**

2021-12-21 04:55

MOT test number

830501877779

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16**

2021-12-21 04:55

MOT test number

759893112791

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2020-12-24 10:57

MOT test number

758930774264

Result

✓ Passed

Advice Play in offside top strut mounting**Advice** Central Exhaust mounting defective (6.1.2 (a))**Advice** Play in nearside top strut mounting**MOT #14**

2020-12-24 09:56

MOT test number

242694857922

Result

✗ Failed

Advice Play in offside top strut mounting**MAJOR** Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Play in nearside top strut mounting**MAJOR** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Central Exhaust mounting defective (6.1.2 (a))**MOT #13**

2019-06-24 12:16

MOT test number

671191942178

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Central Exhaust mounting defective (6.1.2 (a))

**MOT #12**

2018-06-22 10:31

MOT test number

221562425397

Result

✓ Passed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Offside Rear Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear tyres cracked/perished

MOT #11

2017-06-22 10:56

MOT test number

308780008486

Result

✓ Passed

Advice Centre exhaust bracket broken but still supported by additional mounts

Advice Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

MOT #10

2016-06-16 11:00

MOT test number

334758488039

Result

✓ Passed

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #9

2015-06-18 10:21

MOT test number

767379965182

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2014-06-18 10:52**MOT test number** 136779064171**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #7 2014-06-18 10:52**MOT test number** 718119264128**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6 2013-06-26 13:35**MOT test number** 619097673101**Result** ✓ Passed

- Notice** Engine oil leak
- Notice** N/S Front tyre wearing low
- Notice** Exhaust centre bracket broken

**MOT #5** 2013-06-25 11:30**MOT test number** 145136073123**Result** ✗ Failed**Notice** O/S Rear tyre has nail in tread**Notice** Exhaust centre bracket broken**Notice** N/S Front tyre wearing low**Fail** Emissions not tested (7.0)**Notice** Engine oil leak**Notice** MIL illuminated**MOT #4** 2012-06-22 11:25**MOT test number** 906064072114**Result** ✓ Passed**Notice** Nearside front tyre worn outer edge**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Oil leak**Notice** Front discs worn**Notice** Oil warning lit?**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Front pads appear to be getting low**MOT #3** 2011-06-20 12:06**MOT test number** 847091971163**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-06-21 17:32
MOT test number	622622870162
Result	✓ Passed
MOT #1	2009-06-23 15:40
MOT test number	201664179174
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-06-23
Last registration	2024-01-04
Complete history	See info



Registration #1	2006-06-23	12 mi
Registration #2	2009-06-23	29.574 mi
Registration #3	2010-06-21	38.992 mi
Registration #4	2011-06-20	46.371 mi
Registration #5	2012-06-22	50.247 mi
Registration #6	2013-06-25	53.242 mi
Registration #7	2013-06-26	53.245 mi
Registration #8	2014-06-18	57.030 mi
Registration #9	2015-06-18	61.531 mi
Registration #10	2016-06-16	65.463 mi
Registration #11	2017-06-22	69.008 mi
Registration #12	2018-06-20	72.553 mi
Registration #13	2019-06-19	76.098 mi
Registration #14	2020-06-18	79.643 mi
Registration #15	2021-06-17	83.188 mi
Registration #16	2022-06-16	86.733 mi
Registration #17	2023-06-15	90.278 mi
Registration #18	2024-01-04	93.823 mi
Registration #19	2024-01-04	93.823 mi
Registration #20	2024-01-04	93.823 mi
Registration #21	2024-01-04	93.823 mi
Registration #22	2024-01-04	93.823 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 051011